

Trident Auto Service Centre Pte Ltd

8 Kaki Bukit Ave 4, #02-42

Premier @ Kaki Bukit (Gate 1)

Singapore 415875

Tel: 63441918

Date : 11/10/2022

Vehicle : SMH8509B

Make/Model : Toyota Prius

ORD : 2019

Chassis : ZVW508086009

ODO :

ACC Date : 10/10/2022

China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road #15-00, Springleaf Tower

Singapore 079909

Estimate

S/N	Qty	Description & Specification	Amount S\$
List Items			
1	1	Front Bonnet	\$886.90 Dent / 880
2	1	Front Bonnet Lock	\$158.90 ? / Dent 150
3	1	Front Bonner Insulator	\$296.80 * X nn
4	2	Bonnet Hinger	\$173.60 ? X nn
5	1	Front Headlamp RH	\$1,895.60 ? BR - 1800
6	1	Front Bumper	\$1,339.78 cut R
7	1	Front Bumper Logo	\$91.80 cut / 50
Total			\$4,843.38 2880
Less 25%			\$1,210.85 720
List Total			\$3,632.54 2160
S/Nett Items			
1	1 set	Front Bumper Clip nec	\$80.00 40 ✓
2	1 set	Bonnet Insulator Clip nn	\$60.00 X
S/Nett Total			\$140.00 40
Labour			
1		To panel beating, removal and replacing parts	\$600.00 200
2		To putty and respray on accident portion	\$600.00 400
3		To check wiring & focus headlamp	\$80.00 X30
Labour Total			\$1,280.00 630
Grand Total			\$5,052.54 2830

20% = 566

Final T = 2260 //

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2 days 11/10/2022
L/S 18/10 1430