

Step (CLKK)
19/10/22, 1A.mL
P/P
4 J/S

SERVICE ESTIMATE

44988 - C00001 SL: SERVICE SALES - PC
Ms Low Su Lin Yvonne
151 Pavilion Circle

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 13/10/2022
WIP No. . : 45511
Veh.In/Out:
*Tel.No. . : Mobile: 96752756
Reg.No. . : SFP1777E
Reg.date . : 29/11/2017
Mileage .. : 0
Chassis No: SAJAB4AN8JCP25671

Singapore 658563

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Ms Low Su Lin Yvonne

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR BOOTLID, VALANCE REAR, REAR BUMPER BEAM, SENSORS, TAILLAMP, BOOTLAMP, REAR EXHAUST, ETC	0	6500.00	0		6,500.00	S
	<i>1300 x 1.5</i>		<i>1950 ✓</i>				
800	TO SPRAYPAINT ON REAR BUMPER, BOOTLID, REAR FENDER LH, BUMPER BEAM, ETC	0	4000.00	0		4,000.00	S
	<i>1800</i>		<i>2000 ✓</i>				
802	TO REMOVE, REFIT & TRANSFER BOOTLID COMPONENTS	0	500.00	X0		500.00	S
R06	NUMBER PLATE & HOLDER	0	120.00	X0		120.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	621.00	X0		621.00	S
	COVER-BUMPER REAR <i>BR</i>	1.0 EA	1325.30	✓	1192.77	1,325.30	S
	PANEL-VALANC <i>177</i>	1.0 EA	609.80	✓	548.82	609.80	S

SERVICE ESTIMATE

44988 - C00001 SL: SERVICE SALES - PC
 Ms Low Su Lin Yvonne
 151 Pavilion Circle

Singapore 658563

Closed by : Paul Ong Qing Yong
 Svc Consultant :
 Remarks : Ms Low Su Lin Yvonne

GST Reg.No:M28920628X
 0 Page 2

Inv.No. . . : B&P
 Inv.date. . : 13/10/2022
 WIP No. . . : 45511
 Veh.In/Out:
 *Tel.No. . . : Mobile: 96752756
 Reg.No. . . : SFP1777E
 Reg.date . . : 29/11/2017
 Mileage ... : 0
 Chassis No: SAJAB4AN8JCP25671

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
	MOUNTING-BRACKET LH ¹ X NN		1.0 EA	143.00			143.00	S
	MOUNTING-BRACKET RH ¹ X NN		1.0 EA	143.00			143.00	S
	TOW COVER REAR XE ^{CR4}		1.0 EA	37.20	✓ 33.48		37.20	S
	CAP-END RH ¹ X NN		1.0 EA	24.00			24.00	S
	CAP-END LH ¹ X NN		1.0 EA	24.00			24.00	S
	MOUNTING-BRACKET CTR ¹ X NN		1.0 EA	120.00			120.00	S
	PIPE&SILENCR X NN		1.0 EA	1787.10			1,787.10	S
	CLAMP X NN		1.0 EA	99.20			99.20	S
	HEATSHIELD LH X NN		1.0 EA	271.60			271.60	S
	HEATSHIELD LH X NN		1.0 EA	65.90			65.90	S
	TRUNK LIP XE X R		1.0 EA	1858.10			1,858.10	S
	BUMPER BEAM REAR XE ¹ BT		1.0 EA	753.50	✓ 678.15		753.50	S
	BADGE REAR "XE" - ^{nc}		1.0 EA	136.90	✓ 123.21		136.90	S
	BADGE - ^{nc}		1.0 EA	250.60	✓ 225.54		250.60	S
	BADGE - ^{nc}		1.0 EA	131.60	✓ 118.44		131.60	S
	LAMP-TAIL LH - ^{BR}		1.0 EA	593.40	✓ 534.06		593.40	S
	FOG LAMP REAR LH XE - ^{BR}		1.0 EA	443.40	✓ 399.06		443.40	S

SERVICE ESTIMATE

44988 - C00001 SL: SERVICE SALES - PC
 Ms Low Su Lin Yvonne
 151 Pavilion Circle

Singapore 658563

Closed by : Paul Ong Qing Yong
 Svc Consultant :
 Remarks : Ms Low Su Lin Yvonne

GST Reg.No:M28920628X
 0 Page 3
 Inv.No. . : B&P
 Inv.date. : 13/10/2022
 WIP No. . : 45511
 Veh.In/Out:
 *Tel.No. . : Mobile: 96752756
 Reg.No. . : SFP1777E
 Reg.date . : 29/11/2017
 Mileage .. : 0
 Chassis No: SAJAB4AN8JCP25671

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
	PARKING AID SENSOR R	× NN	4.0 EA	314.80			1,259.20	S
	HARNESS REAR BUMPER	× NN	1.0 EA	532.00			532.00	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Gross Total. 22,349.80
 Net..... 22,349.80
 GST @ 7.0% 1,564.49
 Total..... 23,914.30
 Paid..... 0.00
 Please Pay.. 23,914.30

Labour Total 11,741.00
 Parts Total 10,608.80
 Package Total 0.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated