

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Khong Lin Hui Lynn

Date: 19 Oct 2022

Preliminary Advice

Vehicle No	: PC3069C	Accident Date	: 11/10/2022
Make	: NISSAN NV350	Policy No.	: DMB1SNW00014882203
Assignment Date	: 14/10/2022	Excess	: S\$2,000.00
Date of Inspection	: 17/10/2022	Est. Duration of Repair	: 10
Inspection At	: JIN AUTO SERVICES PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,476.08
Revised Amount	:S\$	11,331.08
Check Items (Estimated)	:S\$	5,130.00
Total	:S\$	16,461.08
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	19,000.00
COE / PARF Rebate	:S\$	5,753.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,247.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Lump Sum Repair

Repairer able to undertake the repair Not Exceeding \$12,000/-

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .