

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 08/10/2022

Estimated repair cost for vehicle no: YQ4552L TOYOTA DYNA 150 5MT

CHASSIS: JHHAGV46X0K001072 (2021)

10/10/2022

TP AIG.

Xiao Tong

S/N	Qty	Items	U/price	Amount
1	1	FRONT BUMPER <i>Delud</i>	\$570.80	\$570.80 ✓
2	1	RH FRONT BUMPER BRACKET <i>Best</i>	\$368.10	\$368.10 ✓ 265
3	1	RH FRONT BUMPER FOG LAMP COVER <i>New</i>	\$121.90	\$121.90 +
4	1	RH FRONT HEADLAMP <i>Delud</i>	\$971.20	\$971.20 ✓
5	1	RH FRONT HEADLAMP LOWER RUBBER <i>New</i>	\$61.10	\$61.10 +
6	1	RH FRONT CORNER PANEL <i>Delud</i>	\$370.10	\$370.10 ✓
7	1	FRONT GRILLE <i>New</i>	\$789.20	\$789.20 +
8	1	FRONT GRILLE LOGO <i>New</i>	\$121.20	\$121.20 +
9	1	RH FRONT DOOR <i>Delud</i>	\$1,718.90	\$1,718.90 1580
10	1	RH FRONT DOOR HINGE <i>New</i>	\$230.30	\$230.30 +
11	1	RH FRONT DOOR CHECKER <i>New</i>	\$268.90	\$268.90 +
12	1	RH FRONT DOOR INNER TRIM BOARD <i>New</i>	\$978.10	\$978.10 +
13	1	RH FRONT DOOR WIND MIRROR <i>Delud</i>	\$678.90	\$678.90 ✓
14	1	RH FRONT STEP PANEL <i>Delud</i>	\$570.10	\$570.10 +
15	1	RH FRONT STEP PANEL GARNISH <i>cracked</i>	\$378.40	\$378.40 295
16	1	RH FRONT UPPER ARM <i>Best</i>	\$990.20	\$990.20 680
17	1	RH FRONT LOWER ARM <i>Best</i>	\$470.10	\$470.10 ✓
18	1	RH FRONT KNUCKLER ARM <i>Delud</i>	\$781.20	\$781.20 ✓
19	1	RH FRONT KNUCKLER ARM BEARING <i>Delud</i>	\$220.80	\$220.80 ✓
20	1	RH FRONT SHOCK ABSORBER <i>Delud</i>	\$278.10	\$278.10 ✓

TOTAL : \$10,937.60
LESS 25 % \$2,734.40
SUB-TOTAL : \$8,203.20

7161.20

5370.90

YQ4552L TOYOTA DYNA

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	RH FRONT RIM <i>ct</i>	\$650.00	\$650.00 250
2	1	RH FRONT TYRE <i>xbl n</i>	\$320.00	\$320.00 +
3	1	RH FRONT CORNER PANEL CLIPS <i>mc</i>	\$40.00	\$40.00 20
4	1	RH FRONT DOOR INNER TRIM BOARD CLIPS <i>xbl n</i>	\$80.00	\$80.00 +

270

TOTAL: \$1,090.00TOTAL PARTS: \$9,293.20Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 LABOUR FOR REMOVE & TRANSFER RH FRONT DOOR FITTING
- 4 TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS
- 5 LABOUR FOR REMOVE & RENEW RH FRONT UNDER CARRIAGE
- 6 TO CONDUCT WHEEL ALIGNMENT

7 Wiring.

10/30

~~\$1,000.00~~ 600
~~\$900.00~~ 500
~~\$200.00~~ 80
~~\$200.00~~ 60
~~\$300.00~~ 220
~~\$150.00~~ 80

Subtotal :- \$2,750.00Total:- \$12,043.20

Adrian L
 1/5 10/10/22.

06 days.

total: 67210.80

y/s: 5710

(5710)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: