



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2303818

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 16/06/2023
Reference CC6/CTI22010231/Aya3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. YP 8389X
Insured Veh. GBE 9410R
Claim No. SNM22D207296/C02
Policy No. DNCVSNW0040702201
Accident Date 10/10/2022
Inspection Date 11/10/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22010231/Aya3q2 Date: 16/06/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBE 9410R	Veh. Inspected	YP 8389X
	Policy No.	DNCVSNW0040702201	Coverage (\$)	0.00
	Claim No.	SNM22D207296/C02	Excess (\$)	0.00
	Assign From		Assign Date	11/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	ISUZU NPR85	c.c	2999
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JAANPR85HJ7100012	Colour	WHITE
	Odometer	185395 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/85 R16	COMFORSER	6 mm
	L/H Front Tyre	195/85 R16	COMFORSER	6 mm
	R/H Rear Tyre	195/85 R16	COMFORSER	6 mm
	L/H Rear Tyre	195/85 R16	COMFORSER	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	10/10/2022	Inspection Date	11/10/2022
	Survey held at	J-MART MOTOR PTE LTD BLK 5 DEFU LANE 10 #01-578 DEFU INDUSTRIAL PARK C SINGAPORE 539186		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 8389X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RH DOOR	BUCKLED	2,160.00	1,265.00
2	RH DOOR HINGES @\$180.00	BENT	180.00	180.00
1	RH DOOR CATCH	DAMAGED	75.00	75.00
1	RH DOOR SIGNAL LAMP	NOT NECESSARY	180.00	-
1	RH DOOR RUBBER	NOT NECESSARY	395.00	-
1	RH DOOR OUTER MOULDING	NOT NECESSARY	230.00	-
1	RH DOOR LOCK	NOT NECESSARY	315.00	-
1	RH TRIMBOARD	DEFORMED	590.00	590.00
1	RH DOOR GARNISH	NOT NECESSARY	230.00	-
1	RH STEP GARNISH	NOT NECESSARY	330.00	-
1	RH DOOR PILLAR	TO REPAIR SEE LABOUR	890.00	-
1	FRT RH CORNER PANEL	DEFORMED	490.00	490.00
1	FRT RH CORNER PANEL CLIPS	NECESSARY	20.00	20.00
1	FRT RH CORNER GARNISH	NOT NECESSARY	75.00	-
1	RH HEADLAMP	NOT NECESSARY	1,016.00	-
1	RH SIDELAMP	NOT NECESSARY	560.00	-
	LESS 15% DISCOUNT		-1,160.40	-393.00
			6,575.60	2,227.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF RH DOOR PILLAR .		800.00	500.00
	SPRAY PAINTING .		800.00	600.00
	WIRING.		30.00	30.00
	TRANSFER DOOR PARTS.		80.00	80.00
			1,710.00	1,210.00
	GRAND TOTAL		8,285.60	3,437.00



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,750.00
---	--	--	----------

Report Ref No. CC6/CTI22010231/Aya3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YP 8389X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

