

SMG 457SR.

TP A19

Xiao Tang

Honda Freed Hybrid

GB71079253.

Rear Bumper	Deformed	925.30 ✓
Rear Bumper Clips.	mm	30(SN) ✓
Rear Bumper Side Holder x 02	mm	$42.4 \times 2 = 84.80$ ✓
Rear Bumper Tow Cover	Not mm	36.80. X
Rear Bumper Reflector x 02.	mm	$44.5 \times 2 = 89$ X
Rear Bumper Inner Garnish x 02	Deformed	60.20
Reverse Sensor	Damaged	$60.2 \times 2 = 120.40$ X
Rear End Panel	Dented	280(SN) 200(SN).
Rear End Panel Top Garnish	Deformed	623.70 ✓
Rear End Panel Top Garnish Clips.	Nec	169.30 ✓
Rear End Panel Sealant.	Nec	20(SN) ✓
Rear End Panel Inner	Repair	60(SN) ✓
		486.30 X

SM G 4575R.

Taillamp x 02	Not Nec	580.4 x 2 = 1160.80. +
Tailgate	Distorted	1180.60. ✓
Tailgate Lock	Damaged	157.60. ✓
Tailgate Weatherstripe.	lt	68.70. ✓
Tailgate Inner Trim Board	Cracked	295.30 ✓
Tailgate Inner Trim Board Clips.	nr	30(SN) ✓
Tailgate Inner Pull Pocket	Delnd	32.40. ✓
Tailgate Outer Chrome Moulding.	Cracked	320.40 ✓
Tailgate Outer Chrome Moulding Clips.	nr	20(SN) ✓
Tailgate Lamp x 02.	Not Nec	368.4 x 2 = 736.80 +
Tailgate Glass Moulding. ?	Nec	145.70 ✓
Tailgate Glass Sealant.		60(SN). ✓
Honda Logo		55.20 ✓
Ford Wordng.	Nec	60.40. ✓
Hybrid Emblem.		54.10. ✓

SMG 4575R.

380(SN).

Rear Camera. Dargel

~~786.90~~ X

Not rec

Rear Fender Inner Trim Board x 2

326.7 x 2 = 653.40 X

Rear Fender Inner Trim Board clips. ^M _W

60(SN) X

Rear Exhaust Pipe.

687.10. X

Rear Exhaust Pipe Mounting

Not

34.90 X

Rec

32.50 X.

Rear Exhaust Pipe Gasket.

4337.70

S.N. 800

3470.16

~~1200~~ 1000

Panel Beating

~~1200~~ 800

Spray Painting.

~~100~~ 30

Wiring.

~~100~~ 50

To remove reuse sensor

~~100~~ 50

To remove rear camera.

~~150~~ 60

To remove upholstery.

~~150~~ 60

To spray tuff coat

~~150~~ 60

To transfer tailgate fittings.

~~180~~ 120

To remove tailgate g(4)

SMG 4515R.

To remove exhaust pipe.

150. X

22300

total: 6522.16

4/s 52K

06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

