

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Alfred Toh

Date: 11 Nov 2022

Preliminary Advice

| | | | |
|--------------------|--|-------------------------|-------------------------|
| Vehicle No | : GBK7775U | Accident Date | : 10/10/2022 |
| Make | : TOYOTA HIACE | Policy No. | : DMCVSNW00138232101 |
| Assignment Date | : 14/10/2022 | Excess | : S\$1,500.00 |
| Date of Inspection | : 17/10/2022 | Est. Duration of Repair | : 6 |
| Inspection At | : DING AUTO PTE LTD (HQ) 176 SIN MING DRIVE #04-06, SIN MING AUTOCARE SINGAPORE 575721 | | |

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|----------------|--|
| Repairer's Estimate (Gross) | :S\$ 10,225.43 | (Estimate \$9,480.43 + Supplementary \$745.00) |
| Revised Amount | :S\$ 5,230.18 | |
| Check Items (Estimated) | :S\$ 2,770.00 | |
| Total | :S\$ 8,000.18 | |
| Lump Sum Repair | :S\$ | |

Total Loss Consideration

| | | |
|--------------------|------|-----------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 87,000.00 |
| COE / PARF Rebate | :S\$ | 21,789.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 65,211.00 |

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.