

ASS. REG. BY:

REF: C72/

ASSIGNMENT

Kenneth

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Ding

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 1500

(Client's Record)

Make of Vch: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: 887k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 1-B-1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBK 7775U Yr Regn: 11, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or ANMake: Toy Hiaa c.c. 2754Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GDM 201 2014363Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: 8Rim / STD A/Rim orTyre Size: F: 245/40 8R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kapsen

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 4 mmL/Bal. 6 mm L/Bal. 4 mmD.O.A. 10/10/22 D.O.I. 17/10/2022Survey held at ✓Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1) Check modified bonnet & let home insured??
Battery flag

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation

) S + RS \$

) Fuel

) Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Estimate Repair

Ding Auto Pte Ltd
Sin Ming Industrial Est. Sec C, Blk
10, #01-20
575645

Insurer Reference:
Repairer Reference: 052988
Date calculated: 13/10/2022 3:20 PM



Full Report
Registration: GBK7775U
Printed: 13/10/2022 3:20 PM

Summary Information

Claim		Work Provider:	China Taiping Insurance
Location:	Singapore (SG)		(Singapore) Pte Ltd
		Currency:	SGD
Printed by:	Ding Auto	Date of Incident:	10/10/22
Claim Reference:		Hire Car Start:	
Estimated Repair Time:		Hire Car End:	
Actual Repair Days:			

Vehicle Details

Vehicle
Manufacturer: TOYOTA
Model: HIACE
Sub Model: BASE MODEL
Model Sheet Number: 70 E4 01
Registration: GBK7775U
VIN number:
Odometer: 118782
Model Specs
2.8 LTR 130KW

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Not Authorized
Repairing B & Repairing
Ex 81500h
6 days

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
B091	RENEW L/F WING (BUMPER AND HEADLAMP REMOVED) INCLUDES: R + R WING, CONVERT ATTACHED PARTS		7.0	29.40
B091	RENEW R/F WING (BUMPER AND HEADLAMP REMOVED) INCLUDES: R + R WING, CONVERT ATTACHED PARTS		2.0	8.40
B020)	RENEW FRONT BUMPER REINFORCEMENT		3.0	12.60
B020	RENEW FRONT BUMPER (RADIATOR GRILLE REMOVED) INCLUDES: FRONT BUMPER AND REQUIRED ATTACHED PARTS R + R		7.0	29.40
NO NUMBER	R + R L/F BUMPER MOUNTING		1.0	4.20
NO NUMBER	R + R R/F BUMPER MOUNTING		1.0	4.20
NO NUMBER	R + R CENTRE LOWER RADIATOR GRILLE		2.0	8.40
B030	R + R RADIATOR GRILLE		2.0	8.40
B040	R + R HEADLAMPS (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMPS		4.0	16.80

	Description	WU	Price SGD
1	RENEW BONNET INCLUDES: ASS ATTACHED PARTS AND IF NECE RENEW	3.0	12.60
B080	R + R BONNET HINGE/S	1.0	4.20
NO NUMBER	RENEW AIR CHANNEL	6.0	25.20
B135	RENEW FR/LWR CROSSMEMBER	8.0	33.60
B125	RENEW FRONT LOCK CARRIER	5.0	21.00
NO NUMBER	R + R L/F CROSS MEMBER BRKT	5.0	21.00
NO NUMBER	R + R R/F CROSS MEMBER BRKT	5.0	21.00
M010)	R + R RADIATOR (BUMPER REMOVED) INCLUDES: INTERCOOLER AND ELECTRIC FAN CPL REMOVE AND REFIT. COOLING SYSTEM BLEED	15.0	63.00
M150)	RENEW CHARGE AIR COOLER (REMOVED)	1.0	4.20
	Labour Cost	Hrs	WU
	Panel / Mechanical Labour	7.80	78.0
	Total of Labour		327.60

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h	
Code	Description	WU	Price SGD
	BONNET NEW PART PAINTING	16.0	
	L/F WING NEW PART PAINTING	9.0	
	R/F WING NEW PART PAINTING	9.0	
	CTR FRT PANEL STRUT SURFACE PAINT	4.0	
	FRT PANEL C-MEMBER SURFACE PAINT	5.0	
	L/F C-MEMBER BRACKET SURFACE PAINT	5.0	
	R/F C-MEMBER BRACKET SURFACE PAINT	5.0	
	FRT LOCK CARRIER CPL SURFACE PAINT	4.0	
	AIR DUCT SURFACE PAINT	4.0	
	FRT LWR CROSSMEMBER SURFACE PAINT	5.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	40.70
0741	L/F WING NEW PART PAINTING	14.91
0742	R/F WING NEW PART PAINTING	14.91
0988	CTR FRT PANEL STRUT SURFACE PAINT	1.94
1003	FRT PANEL C-MEMBER SURFACE PAINT	4.40
1005	L/F C-MEMBER BRACKET SURFACE PAINT	4.40
1006	R/F C-MEMBER BRACKET SURFACE PAINT	4.40
1015	FRT LOCK CARRIER CPL SURFACE PAINT	2.64
1310	AIR DUCT SURFACE PAINT	1.23
1320	FRT LWR CROSSMEMBER SURFACE PAINT	4.40

Labour Cost - Paint

Factor
Time Paint
Preparation Main Work Metal
Total

42.00 SGD/h

Hrs

WU

Price SGD

66.0

0.80

8.0

33.60

10 WU/h

7.40

74.0

310.80

Material Cost - Paint

New Part Painting
Surface-/Blend Paint
Material-constant Metal
Total

Price SGD

70.52

23.41

18.10

112.03

Spare Parts

prices as at 2015-06-01/01

Code	Description	Part Number	Part Source	Price SGD
0253	L/F BMPR BLANK CAP	53113 26060	Original	nn 40.00 X
0254	R/F BMPR BLANK CAP	53112 26060	Original	nn 40.00 X
0257	FRONT NUMBER PLATE	KNPL3	Original	nn 30.00 ✓
0281	FRT NO PLATE REINF	52114 26020	Original	nn 30.00 X
0293	FRONT BUMPER	52119 26651	Original	CM 280.00 ✓
0294	L/F BUMPER COVER	52127 26120	Original	nn 20.00 X
0317	R/F BUMPER COVER	52127 26120	Original	nn 20.00 X
0318	L/F INNER COVER BRKT	52116 26170	Original	nn 55.00 ✓
0331	R/F INNER COVER BRKT	52115 26170	Original	nn 55.00 ✓
0341	FRT BUMPER SUPPORT	52131 26020	Original	R 185.00 X
0410	FT BUMPER AIR GRILLE	53112 26070	Original	nn 160.00 X
0411	LWR RADIATOR GRILLE	53111 26510	Original	nn 265.00 X
0413	UPP RADIATOR GRILLE	53111 26500	Original	nn 180.00 X
0431	GRILLE BACKING	53112 26090	Original	nn 285.00 X
0471	GRILLE BADGE	90975 02086	Original	nn 70.00 X
0475	BONNET	53301 26080	Original	CM 300.00 ✓
0476	LEFT BONNET HINGE	53420 26040	Original	R 35.00 X
0493	RIGHT BONNET HINGE	53410 26040	Original	R 35.00 X
0561	BONNET LOCK	53510 26060	Original	nn 65.00 ✓
0562	LEFT HEADLAMP ASSY	81170 26731	Original	nn 990.00 ✓
0741	RIGHT HEADLAMP ASSY	81130 26731	Original	nn 990.00 ✓
0742	L/F WING	53802 26021	Original	R 80.00 X
0988	R/F WING	53801 26011	Original	R 80.00 X
1003	CTR FRT PANEL STRUT	53209 26100	Original	R 55.00 ✓
1005	FRT PANEL C-MEMBER	57053 26030	Original	R 120.00 X
1006	L/F C-MEMBER BRACKET	53036 26020	Original	R 50.00 X
1015	R/F C-MEMBER BRACKET	58127 26050	Original	R 50.00 X
1310	FRT LOCK CARRIER CPL	53201 26082	Original	R 220.00 ✓
1320	AIR DUCT	55757 26040	Original	nn 105.00 X
7750	FRT LWR CROSSMEMBER	57109 26021	Original	R 180.00 X
7761	GRILLE	16546 75010	Original	nn 150.00 X
8405	RADIATOR	16400 11A40	Original	780.00 ?
8739	EXPANSION TANK	16470 75123	Original	155.00 ?
1000	HEAT EXCHANGER	17940 30051	Original	680.00 ?
1001	FRT RADAR SENSOR CPL	RADAR SENSOR	Original	580.00 ?
1002	RADAR SENSOR	RADAR SENSOR	Original	nn 480.00 X
1003	GARNISH			
1002	INTERCOOLER HOUSING	INTERCOOLER	Original	R 140.00 X
1003	WIPER TANK CPL	WIPER TANK	Original	75.00 ?

Description
WING BRACKET RH
WING BRACKET LH

Part Number
WING BRACKET
WING BRACKET

Part Source
Original
Original

Price SGD
60.00
60.00

OEM Parts
Non-OEM Parts
Used parts

Savings
Subtotal

0.00
8,230.00

Total

8,230.00

Extras

Code	Description	Price SGD
1006	SENSOR RE-SETTING RADAR SENSOR	(Am) 500.00* ?
	Total Extras	500.00

Final Calculation

	SGD	SGD
Parts	8,230.00	
Actual Parts		8,230.00
Labour Time Base 10 WU/h		
Total 78.0 WU X 42.00 SGD/h	327.60	
Total of Labour		327.60
Total Of Extras		500.00
Paint Work Time Base 10 WU/h		
Labour Cost 74.0 WU X 42.00 SGD/h	310.80	
Material Cost	112.03	
Total Paint Including Material		422.83
Repair Cost Excludes GST		9,480.43
GST (+7.0%)		663.63
Repair Cost Included GST		10,144.06

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 12/10/2022 15:07 (SGT)
Reported by Driver
Date of Accident 10/10/2022 19:00 (SGT)
Exact Location of Accident Singapore
Additional Location Information PIE CHANGI BEFORE KPE EXIT
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBK7775U

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner SSL LIMOUSINE PTE LTD
Company Reg No 2XXXXX894E
Email Address GARYONG66@ICLOUD.COM
Mobile Phone No (Phone) +65-97458239
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Toyota
Model Hiace
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Commercial vehicle
Transmission Auto
CC 2754

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number DMCVSNW00138232101

DRIVER

Name of Driver MUHAMMAD AZAHARI BIN ZAINAL
NRIC No SXXXX539H
Date Of Birth 18/10/1997
Occupation Outdoor

