

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0869/2022/EQ
DATE : 10-Oct-22
WIP : 45338

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/10/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

4 days - ok - Jy - 14 Dec 22

OWNER'S NAME : MR CHEONG HON CHOY, DARREN
ADDRESS : TRELLIS TOWER, 700 LORONG TOA PAYOH
#09-09
SINGAPORE 319773
TELEPHONE : HP +65 90252393
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070172452-01
VEHICLE NO : **SCN 3909 A**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 14/12/2020
ENGINE NO : DEM 025271
CHASSIS NO : WAUZZZF50MA000615
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Sep-22
PLACE OF ACCIDENT : TRELLIS TOWER, 700 TOA PAYOH LORONG 1,
BASEMENT CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCN 3909 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	\$	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	\$	1,000.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	1,900.00	\$	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 5,372.00	\$	3,022.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCN 3909 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,493.00	\$ 1,994.40
2	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 293.00	\$ 234.00
3	FRONT BUMPER AIR GUIDE - LH	1	\$ 72.00	
4	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 151.00	\$ 120.40
5	FRONT BUMPER TRIM - LH	1	\$ 54.00	
6	FRONT BUMPER GUIDE SECTION - LH	1	\$ 41.00	
7	FRONT FENDER - LH	1	\$ 1,189.00	\$ 951.20
8	FRONT FENDER ATTACHMENT PARTS	1	\$ 55.00	
9	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 83.00	
10	FRONT FENDER BRACKET - LH REAR	1	\$ 65.00	
11	FRONT FENDER BRACKET - LH CENTER	2	\$ 79.00	
12	FRONT FENDER BRACE - LH	1	\$ 132.00	
13	FRONT FENDER RIVET	10	\$ 38.00	
14	FRONT FENDER LEDGE COVER - SHORT	1	\$ 18.00	
15	FRONT FENDER LEDGE COVER - LONG	1	\$ 40.00	
16	FRONT FENDER CHROME TRIM - LH	1	\$ 171.00	\$ 136.40
17	FRONT WHEEL SPOILER	1	\$ 82.00	
18	FRONT WHEEL SPOILER STONE CHIP GUARD - LH	1	\$ 57.00	
19	HEADLIGHT - LH	1	\$ 8,172.00	\$ 6,537.60
20	FRONT PARKING AID SENSOR - OUTER	1	\$ 266.00	
SUB TOTAL SPARE PARTS		:	\$ 13,551.00	\$ 9,974.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCN 3909 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 9,974.00
21	FRONT PARKING AID SENSOR - SIDE	1	\$ 266.00	
22	FRONT PARKING AID SEAL RING	6	\$ 15.00	
23	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 14,132.00	\$ 9,974.00
TOTAL LABOUR CHARGES		:	\$ 5,372.00	\$ 3,022.00
GRAND TOTAL		:	\$ 19,504.00	\$ 12,996.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-05/12/22