

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CC3/AIG22010244/ANY3E2  
**Date:** 02/03/2023**REFERENCE**Insured/Claimant: BENJAMIN TOH LIK HONG Policy No: 7210142500  
Date of Loss: 13/10/2022 Nature of Claim: OD Claim No: 8845066431SG**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLX7011D**  
Make & Model: AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) Engine No: CZDC54128  
Reg. Date: 23/11/2021 (Man. Year: 2021) Chassis No: WAUZZZF3XN1038143  
Colour: White Odometer: 11155 km  
Engine Capacity: 1395 cc  
Market Value/New Car Price: S\$180,000.00  
Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes**CONDITION OF TYRES**Front Tyre Size: 215/65 R17 Rear Tyre Size: 215/65 R17  
Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm  
Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	14,469.00	5,935.20	8,533.80	58.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,132.00	5,612.00	6,520.00	53.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>26,601.00</b>	<b>11,547.20</b>	<b>15,053.80</b>	<b>56.59</b>
<b>- Excess (S\$)</b>	400.00	400.00	0.00	0.00
<b>(S\$)</b>	26,201.00	11,147.20	15,053.80	57.46
<b>+ GST 8.00/8.00% (S\$)</b>	2,096.08	891.78	1,204.30	57.45
<b>Nett Amount (S\$)</b>	<b>28,297.08</b>	<b>12,038.98</b>	<b>16,258.10</b>	<b>57.46</b>

**INSPECTION**Date of Assignment: 17/10/2022  
Date Inspected: 14/10/2022 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699  
Estimated Period of Repair: 7.0 days**Adjuster:** ADRIAN LING**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,738.00 FS	*- FS
2	1		*REAR BUMPER SPOILER	Cut	510.00 FS	*408.00 FS
3	1		*REAR BUMPER GRILLE - RH	Not Necessary	170.00 FS	*- FS
4	1		*REAR PARKING AID SENSOR SUPPORT - RH	Not Necessary	28.00 FS	*- FS
5	1		*REAR BUMPER ADAPTER - RH	Not Necessary	95.00 FS	*- FS
6	1		*REAR BUMPER CROSS REINFORCEMENT - CENTER	Not Necessary	108.00 FS	*- FS
7	1		*REAR BUMPER BRACKET	Not Necessary	53.00 FS	*- FS
8	1		*REAR BUMPER REFLECTOR - RH	Not Necessary	46.00 FS	*- FS
9	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	71.00 FS	*- FS
10	1		*REAR UNDERBODY TRIM - RH	Not Necessary	58.00 FS	*- FS
11	2		*REAR WHEEL COVER - LH / RH	Necessary	1,132.00 FS	*904.80 FS
12	1		*REAR DOOR - RH	Dented	3,028.00 FS	*2,422.40 FS
13	1		*REAR OUTER DOOR SEAL - RH	Necessary	151.00 FS	*120.40 FS
14	1		*REAR DOOR CATCH	Damaged	134.00 FS	*106.80 FS
15	1		*REAR INNER DOOR SEAL	Not Necessary	213.00 FS	*- FS
16	1		*REAR SILL PANEL SEAL - RH	Not Necessary	151.00 FS	*- FS
17	1		*REAR DOOR COVER - RH	Distorted	368.00 FS	*294.00 FS
18	1		*REAR DOOR SIDE MEMBER TRIM - RH	Not Necessary	189.00 FS	*- FS
19	1		*REAR WHEEL SPOILER - RH	Not Necessary	44.00 FS	*- FS
20	1		*REAR WHEEL HOUSING LINER - RH	Not Necessary	262.00 FS	*- FS
21	1		*FRONT DOOR - RH	Repair	3,028.00 FS	*- FS
22	1		*FRONT OUTER DOOR SEAL - RH	Not Necessary	185.00 FS	*- FS
23	1		*FRONT DOOR CATCH	Not Necessary	134.00 FS	*- FS
24	1		*FRONT DOOR COVER - RH	Deformed	390.00 FS	*312.00 FS
25	1		*FRONT DOOR HINGE HALF - UPPER PART - RH LOWER	Not Necessary	53.00 FS	*- FS
26	1		*FRONT DOOR HINGE HALF - LOWER PART - RH LOWER	Not Necessary	49.00 FS	*- FS
27	1		*REAR ALUMINIUM RIM	Cut	1,414.00 FS	*1,131.20 FS
28	1		*REAR ALUMINIUM RIM RUBBER VALVE	Not Necessary	4.00 FS	*- FS
29	1		*SUNDRIES	Necessary	400.00 FS	*25.20 FS
30	1		*DOUBLE-SIDED ADHESIVE TAPE (Supplementary)	Necessary	263.00 FS	*210.40 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>14,469.00</b>	<b>5,935.20</b>
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES, INSPECT FOR DAMAGES	New	800.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER, RHS REAR DOOR AND RHS FRONT DOOR. TO REPAIR RHS REAR FENDER, RHS SILL PANEL AND DOOR ENTRANCES. RE-ORGANIZE CRASH MANAGEMENT CRASH COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,000.00	1,500.00
3	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR, RHS FRONT DOOR, DOOR HINGES, 2 DOOR COVER, DOOR ENTRANCES, RHS SILL PANEL AND BOTH REAR WHEEL ARCH TRIMS	New	6,500.00	3,000.00
4	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
<b>Gross Labour Cost (\$)</b>			<b>12,132.00</b>	<b>5,612.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >