

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SKX 9552H Yr Regn: 4/11/16
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Camry c.c. 1998
 Colour: Silver A/C: Insured / Std / Nil / NA
 Sp. Reading: 169715 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/N: M1R0530K5100105098
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / SDRim / STD A/Rim or
 Tyre Size: F: 205/50R16
 R: 17

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Ball. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 G/A / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

BS / DUN / EXNOVA G / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or .

Front Rear
 R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. 4 mm L/Bal. 4 mm
 D.O.A. 7/10/22 D.O.I. 7/10/22
 Survey held at Morg
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooktop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-78X

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B.H. (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL



Main Office : No. 22, Jalan Kilang, Singapore 150419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0098804-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading

Dealing in New/Used Cars, Hire Purchase & Insurance



TP INSURER:
UNKNOWN

Allianz Insurance Singapore Pte. Ltd. (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	07/10/2022
Vehicle Reg. No.:	SKX9552H	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA CAMRY, 2.0 (A)	Vehicle Reg. Date:	04/01/2016
Vehicle Colour:	SILVER	Chassis No:	MR053DK5100105098
Engine No:	6ARP111774		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	4,068.90
Miscellaneous Items	40.00
Labour	1,910.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	6,018.90
+ GST 7.00% (\$\$)	421.32
Nett Amount (\$\$)	6,440.22

This claim is handled by: KEONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Oct 2022)
 Parts: 143 TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKX9552H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT / <i>DD</i>	0.00	0.00	*550.00 F
2	1		*REAR BOOT LOGO / <i>NPC</i>	0.00	0.00	*38.00 F
3	1		*REAR BOOT EMBLEM CAMRY / <i>NPC</i>	0.00	0.00	*40.00 F
4	1		*REAR BOOT EMBLEM 2.0 / <i>NPC</i>	0.00	0.00	*35.00 F
5	1		*REAR BOOT EMBLEM D-45 / <i>NPC</i>	0.00	0.00	*35.00 F
6	2		*REAR BOOT LAMP L+R / <i>X</i>	0.00	0.00	*380.00 F
7	1		*REAR BOOT LOCK / <i>X</i>	0.00	0.00	*240.00 F
8	1		*REAR BOOT CATCH / <i>X</i>	0.00	0.00	*30.00 F
9	1		*REAR BOOT RUBBER / <i>X</i>	0.00	0.00	*75.00 F
10	2		*REAR LAMP L+R / <i>X</i>	0.00	0.00	*460.00 F
11	1		*REAR END PANEL / <i>X</i>	0.00	0.00	*395.00 F
12	1		*REAR END PANEL TRIM / <i>X</i>	0.00	0.00	*120.00 F
13	1		*REAR BUMPER / <i>DD</i>	0.00	0.00	*350.00 F
14	2		*REAR BUMPER SENSOR L+R / <i>X</i>	0.00	0.00	*400.00 F
15	1		*REAR BUMPER REINFORCEMENT / <i>X</i>	0.00	0.00	*210.00 F
16	2		*REAR BUMPER BRACKET L+R / <i>X</i>	0.00	0.00	*96.00 F
17	2		*REAR BUMPER RETAINER L+R / <i>X</i>	0.00	0.00	*110.00 F
18	10		*REAR BUMPER CLIPS / <i>NPC</i>	0.00	0.00	*25.00 F
19	1		*REAR KEYLESS SENSOR / <i>X</i>	0.00	0.00	*110.00 F

F=Franchise part.

Sub Total (S\$) 3,699.00
 + Margin on L,N Items 10.00% (S\$) 369.90

Total Parts (S\$) 4,068.90

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Qty	Particulars	Amount
<u>Miscellaneous Items</u>		
1	2 REAR CHASSIS MEMBER L+R - TO REPAIR	-
2	2 REAR FENDER L+R - TO REPAIR	-
3	1 REAR FLOOR PANEL - TO REPAIR	-
4	1 REAR NUMBER PLATE	-
		X 40.00
Sub Total (\$\$)		40.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CUT & WELD REAR END PANEL, TO REPAIR REAR FENDER L+R, REAR FLOOR PANEL, REAR CHASSIS MEMBER, TO REMOVE & REFIX DAMAGED PARTS & REALIGN AFFECTED AREAS	New	800 840.00
2	TO SPRAY AFFECTED AREAS	New	600 850.00
3	TO REMOVE & REFIX LUGGAGE COMPARTMENT SIDE GARNISH, SIDE TRIM BOARD, CARPET & OTHER ATTACHMENT PARTS	New	50 100.00
4	TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE	New	30 60.00
5	TO RUST PROOF AFFECTED AREAS	New	30 60.00
Gross Labour Cost (\$\$)			1,910.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve (LKK)
14/11/22, 10:30am

LL R

L/S

My BOL G
5 dyp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: