

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22010253/UVCQ2
Date: 26/10/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00048852200
Claimant Vehicle No :	SBM818R	Insured Vehicle No :	GX4214P
Date of Loss:	13/10/2022	Nature of Claim:	TP
		Claim No:	SNM22D207357/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBM818R	Engine No:	10296322014986
Make & Model:	MERCEDES-BENZ 200E, 2.0 (A)	Chassis No:	WDB1240212B179946
Reg. Date:	14/03/1990 (Man. Year: 1990)	Odometer:	137554 km
Colour:	Blue		
Engine Capacity:	1996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,179.00	2,276.10	1,902.90	45.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	980.00	370.00	27.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,529.00	3,256.10	2,272.90	41.11
Approved Total (Overridden) (S\$)		2,600.00		
Nett Amount (S\$)	5,529.00	2,600.00	2,929.00	52.98

INSPECTION

Date of Assignment:	19/10/2022	
Date Inspected:	18/10/2022 Inspected At:	23 Kaki Bukit Ave 5 #04-01 (SOUTH WING) Singapore 415933
Estimated Period of Repair:	4.0 days	Repairer: Automobile Hub Enterprise

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Oct 2022)
Parts:	143	MERCEDES-BENZ 200E 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBM818R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	1,215.00 FL	*1,215.00 FL
2	2		*FRONT BUMPER SIDE HOLDER	Cracked	112.00 FL	*112.00 FL
3	1		*FRONT BUMPER PAD	Cracked	368.00 FL	*368.00 FL
4	2		*FRONT BUMPER CHROME MOULDING	Bent / Necessary	486.00 FL	*486.00 FL
5	1		*FRONT BUMPER BEAM	Twisted	183.00 FL	*183.00 FL
6	1		*HEADLAMP RH	Not Necessary	987.00 FL	*- FL
7	1		*FRONT RH SIGNAL LAMP	Cracked	219.00 FL	*165.00 FL
8	1		*FRONT RH FENDER	Repair	874.00 FL	*- FL
9	1		*FRONT RH FENDER INNER SHIELD	Not Necessary	104.00 FL	*- FL
10	1		*FRONT RH FENDER CHROME MOULDING	Not Necessary	62.00 FL	*- FL
11	1		*SET FRONT FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,640.00	2,529.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	461.00	252.90
Total Parts (\$\$)	4,179.00	2,276.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVE AND REFIT PARTS	New	600.00	400.00
2	SPRAY PAINTING TO AFFECTED AREA	New	700.00	550.00
3	WIRING CHECK	New	50.00	30.00
Gross Labour Cost (\$\$)			1,350.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >