

# HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit  
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT  
AUTOWORK PTE LTD

DATE : 18.10.2022

TO : CHINA TAIPING MOTOR CLAIMS DEPTS  
VEHICLE NO : SMH3789S  
MODEL : TOYOTA NOAH  
DATE OF ACCIDENT : 14.10.2022  
TIME OF ACCIDENT : 14:00 HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

## CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER	1	\$ 1,339.31	\$ 1,339.31
2	REAR BUMPER TOW HOOK COVER	1	\$ 28.10	\$ 28.10
3	REAR BUMPER REFLECTOR	2	\$ 125.60	\$ 251.20
4	REAR BUMPER SIDE RETAINER (FRONT)	2	\$ 145.80	\$ 291.60
5	TAILGATE	1	\$ 1,812.70	\$ 1,812.70
6	TAIL GATE EMBLEM 'HYBRID SYNERGY DRIVE'	1	\$ 75.20	\$ 75.20
7	TAILGATE STOPPER	2	\$ 28.60	\$ 57.20
8	TAILGATE INNER LOCK	1	\$ 452.10	\$ 452.10
9	TAILGATE LOWER LOCK	1	\$ 36.70	\$ 36.70
10	TAILGATE BUZZER	1	\$ 96.30	\$ 96.30
11	TAILGATE DETECTOR	1	\$ 175.20	\$ 175.20
12	TAILGATE DETECTOR WIRE HARNESS	1	\$ 287.30	\$ 287.30
13	TAILGATE INNER TRIM	1	\$ 580.30	\$ 580.30
14	TAILGATE INNER HOLDER	1	\$ 65.00	\$ 65.00
15	TAILGATE WEATHER STRIP	1	\$ 375.10	\$ 375.10
16	TAILGATE WINDSCREEN GLASS C/W MOULDING	1	\$ 1,198.70	\$ 1,198.70
17	TAIL LAMP LOWER GARNISH	2	\$ 178.80	\$ 357.60
18	TAIL LAMP LOWER GARNISH RETAINER	2	\$ 160.70	\$ 321.40
19	REAR FENDER INNER TRIM	2	\$ 906.51	\$ <sup>nn</sup> 1,813.02
20	REAR FENDER COWLING	2	\$ 118.70	\$ 237.40
21	REAR END PANEL C/W END EXTEND PANEL	1	\$ 762.20	\$ 762.20
22	REAR END PANEL TOP GARNISH	1	\$ 168.20	\$ 168.20
23	REAR FLOOR MAT	1	\$ 685.10	\$ 685.10

de - 986 ✓

x nn

x nn

x nn

bt ✓

ner ✓

x nn

bt ✓

x nn

~~ner~~ nn

ner ✓

x nn

ner ✓

x nn

cut ✓

x nn

x nn

x nn

x <sup>nn</sup> de - 685 ✓

x nn

ner bt ✓

de ✓

x nn

TO : CHINA TAIPING MOTOR CLAIMS DEPTS  
 VEHICLE NO : SMH3789S  
 MODEL : TOYOTA NOAH  
 DATE OF ACCIDENT : 14.10.2022  
 TIME OF ACCIDENT : 14:00 HRS

24	REAR FLOOR PANEL TOP BOARD	1	\$ 1,165.50	\$ 1,165.50
25	JACK COVER GARNISH	1	\$ 186.00	\$ 186.00

dl 1105 ✓  
 X nn

7177  
 -25%  
 5382.75

TOTAL PRICE \$ 12,818.43  
 LESS 25% \$ 3,204.61  
 SUB TOTAL PRICE \$ 9,613.82

**SPECIAL NETT ITEMS**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS (SET)	1	\$ 80.00	\$ 80.00
2	REAR BUMPER DIFFUSER (SPECIAL TYPE)	1	\$ 1,800.00	\$ 1,800.00
3	TAIL LAMP LOWER GARNISH CLIP (SET)	1	\$ 60.00	\$ 60.00
4	TAILGATE OUTER MOULDING CLIP (SET)	1	\$ 40.00	\$ 40.00
5	TAILGATE INNER TRIM CLIP (SET)	1	\$ 80.00	\$ 80.00
6	TAILGATE TOP INNER TRIM CLIP (SET)	1	\$ 50.00	\$ 50.00
7	TAILGATE SIDE INNER TRIM CLIP (SET)	1	\$ 50.00	\$ 50.00
8	TAILGATE WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00
9	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00
10	TAILGATE WINDSCREEN SOLAR FILM	1	\$ 550.00	\$ 550.00
11	REAR FENDER INNER TRIM CLIP (SET)	1	\$ 80.00	\$ 80.00
12	REAR FENDER INNER COWLING CLIP (SET)	1	\$ 80.00	\$ 80.00
13	REAR END PANEL TOP GARNISH CLIPS (SET)	1	\$ 40.00	\$ 40.00
14	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00
15	JACK COVER GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00
16	JACK	1	\$ 150.00	\$ 150.00
17	REVERSE CAMERA	1	\$ 450.00	\$ 450.00
18	REVERSE SENSOR (2PCS)	1	\$ 250.00	\$ 250.00

300 ✓  
 600 ✓  
 X nn  
 X nn  
 X nn  
 X nn  
 X nn  
 400 ✓  
 300 ✓  
 X nn  
 X nn  
 X nn  
 X nn  
 200 ✓  
 X nn  
 X nn  
 X nn  
 200 nn ✓

TOTAL \$ 4,100.00 920

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	600
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	700
3	TUFF COAT	\$ 250.00	300

TO : CHINA TAIPING MOTOR CLAIMS DEPTS  
 VEHICLE NO : SMH3789S  
 MODEL : TOYOTA NOAH  
 DATE OF ACCIDENT : 14.10.2022  
 TIME OF ACCIDENT : 14:00 HRS

4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	\$ 180.00	60
5	REMOVE AND REFIX REAR AIRCON BLOWER MOTOR	\$ 350.00	X
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	30
7	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING	\$ 80.00	X
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	30
9	REAR CHASSIS ALIGNMENT	\$ 250.00	X
10	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 150.00	120
11	TRANSFER TAILGATE MECHANISM	\$ 120.00	60
12	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X
13	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	\$ 80.00	X
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

1603

TOTAL \$ 4,900.00  
 TOTAL PARTS COST : \$ 13,713.82  
 TOTAL LABOUR COST : \$ 4,900.00  
 TOTAL REPAIR COST : \$ 18,613.82

7905.75

L/S - 6324.60  
 = 6300

*Taufik 97498749/02583561  
 wpd 19/10/22 @ 440pm  
 L/S Resurvey after repair  
 Taufik C/ah auto.com  
 5 days*

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

**IRENE**

SERVICE ADVISOR  
 IRENE  
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: