



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22010260/Eqy3e2	
			Date: 16/11/2022	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 4748P	Veh. Inspected	SMY 1825U	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/10/22/2033	Excess (\$)	0.00	
Assign From	ASHLENE LEE	Assign Date	17/10/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA FIT	c.c	1317	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	GR11024205	Colour	GREY	
Odometer	68441 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	DUNLOP	4 mm	
L/H Front Tyre	185/60 R15	DUNLOP	4 mm	
R/H Rear Tyre	185/60 R15	DUNLOP	4 mm	
L/H Rear Tyre	185/60 R15	DUNLOP	4 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	07/10/2022	Inspection Date	18/10/2022	
Survey held at	ROTOR AUTO ELECTRICAL PTE LTD Blk 3 PIONEER ROAD NORTH #01-21 SINGAPORE 628457			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	