

Xmax 300 FBS6833A

Handlebar ?	\$75
Front mudguard side cover left <i>/ Cut</i>	\$50
Front mudguard side cover right <i>/ Cut</i>	\$50
Brake lever left <i>/ Cut</i>	\$38
Brake lever right <i>/ Cut</i>	\$38
Front side cover left <i>/</i>	\$65
Front lower side cover left <i>/</i>	\$35
Front under cowling left <i>/ Cut</i>	\$50
Front side cover right <i>/</i>	\$65
Front lower side cover right <i>/</i>	\$35
Front under cowling right <i>/</i>	\$50
Lower side panel right <i>/</i>	\$40
Side panel <i>/</i>	\$70
Rear panel left <i>/</i>	\$75
Rear panel right <i>/</i>	\$75
Exhaust protector side <i>/</i>	\$45
Exhaust protector <i>/</i>	\$35

Rear Box <i>/ Cut</i>	\$150
Labour Charge	\$350 <i>300</i>
Fork Alignment ?	\$150
Sub Total	\$1341
GST 7%	\$93.87
Grand Total	\$1434.87

*2-3 Days.
part by part.
After repair photos.
Emo Qian - 82880282
17/10/22*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental parts must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: