



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP22010262/Gwy3e2	
			Date: 20/12/2022	
			Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBJ 6960M	Veh. Inspected	FBS 6833A
	Policy No.		Coverage (\$)	0.00
	Claim No.	IVS22/1746	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	17/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA XMAX	c.c	250
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	MH3SG3920MK002063	Colour	GREY
	Odometer	16057 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	120/70-15	DUNLOP	6 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	140/70-14	DUNLOP	6 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	10/10/2022	Inspection Date	17/10/2022
	Survey held at	ATAN MOTORING SUPPLY PTE LTD BLK 3006 UBI ROAD 1 #01-370 . SINGAPORE 408700		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	