

Xmax 300 FBS6833A

Handlebar ? / bend	\$75
Front mudguard side cover left / cut	\$50
Front mudguard side cover right / cut	\$50
Brake lever left / cut	\$38
Brake lever right / cut	\$38
Front side cover left	\$65
Front lower side cover left	\$35
Front under cowling left / cut	\$50
Front side cover right	\$65
Front lower side cover right	\$35
Front under cowling right	\$50
Lower side panel right	\$40
Side panel	\$70
Rear panel left	\$75
Rear panel right	\$75
Exhaust protector side	\$45
Exhaust protector	\$35

Rear Box / cut	\$150
Labour Charge	\$350 300
Fork Alignment ? X	\$150
Sub Total	\$1341
GST 7%	\$93.87
Grand Total	\$1434.87

2-3 Days.
part by part.
After repair photos.
Emo Qian - 82880282
17/10/22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices for repair confirmation
- Third party repair on "Without Prejudice" basis
- No litigation involved in repair
- Supply of parts to be surveyed and is subject to the relevant insurance Company

Acknowledged by Repairer:
Signature:
Date:

Xmax 300 FBS6833A

Handlebar	\$75
Front mudguard side cover left	\$50
Front mudguard side cover right	\$50
Brake lever left	\$38
Brake lever right	\$38
Front side cover left	\$65
Front lower side cover left	\$35
Front under cowling left	\$50
Front side cover right	\$65
Front lower side cover right	\$35
Front under cowling right	\$50
Lower side panel right	\$40
Side panel	\$70
Rear panel left	\$75
Rear panel right	\$75
Exhaust protector side	\$45
Exhaust protector	\$35
Rim Shaft	\$40
Front Fork Left	\$240
Front Fork Right	\$240
Front Fork Under Bracket	\$320
Rear Box	\$150
Labour Charge	\$300
Sub Total	\$2181
GST 7%	\$152.67
Grand Total	\$2333.67

Bend