

Condition (CON)

(01) Bent (2) Dented (3) Disoriented (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Stuffed (09) Buckled (10) Broken (11) Necessary (12) Missing
(13) Torn (14) Unconfirmed (15) Not Working

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (?)
(4) Not Consistent (NC)

Aug 2005

MOTOR CAR (LH)

Vehicle No: **SJE 3250E**

Left Portion

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door	DD	R	
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1259	995102	Frt LH Door Garnish	51	/	100
1260	991593	Frt LH Door Glass Outer Moulding			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock			
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH			
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1009	991468	Frt Bumper Sponge			
1010	991427	Frt Bumper Protector			
1011	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1029	995153	Frt LH Headlamp Assy			
1031	995088	Frt LH Side Lamp	SCR	R	
1096	995070	Frt LH Fender	DD	R	
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector Emblem	NEC		55

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door			
1290	993282	Rear LH Door Protector			
1291	995194	Rear LH Door Hinge			
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator			
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber			
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock			
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1040	992958	Rear Bumper			
1047	992976	Rear Bumper Bracket			
1048	993068	Rear Bumper Side Retainer			
1049	993045	Rear Bumper Reinforcement			
1050	993077	Rear Bumper Sponge			
1051	993040	Rear Bumper Protector			
1052	993026	Rear Bumper Moulding			
1053	993023	Rear Bumper Lower Spoiler			
1054	993851	Rear LH Taillamp			
1055	993436	Rear LH Fender			
1056	993449	Rear LH Fender Protector			
1057	990247	Sticker			

No of Items: _____ Assessor: _____

REPAIR 3 DAYS

Labour :

Veh. No.
SJE3250E

- 1) Replacing accident damaged parts, knock/jack & straighten accident affected area \$400 300
- 2) Spray painting accident affected areas. \$500
- ~~3) Carry out body cavity preservation on accident affected areas. \$0~~
- 4) Checking electrical wiring & lighting system for proper function. \$30
- ~~5) Replacing reverse sensors. \$0~~
- ~~Removing & installing boot compartment trimming, garnish, etc, in order to carry~~
- ~~6) out necessary repair and replacing rear LH fender inner trim. \$0~~