



# HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E  
 BEDOK NORTH AVE 4,  
 #01-2008/10/12 SINGAPORE 489977  
 TEL: 6441 5655 FAX: 6441 5355/6243 8121  
 R.O.C No: 200104141D GST Reg. No. 20-0104141-D

*not available  
 25/10/22  
 2/5 # 4250  
 4 days  
 Whatsapp: 9777*

TO : 81823573  
 LOH KOH LIANG  
 NO

SINGAPORE  
 TEL: FAX:  
 PH: 81823573  
 ATTN:

## ESTIMATE BILL

Number : EB00006115  
 Date : 15/10/2022  
 Case No : AD00013190  
 Vehicle No : SKS3787M  
 Chassis : RU11017780  
 Year of Mfr : 2015  
 Policy No  
 Model : HONDA VEZEL 1.5G  
 AUTO

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRONT BUMPER <i>cut/dys -</i>	1.0	898.30	20	718.64
2	FRONT BUMPER RETAINER RH <i>one -</i>	1.0	15.00	20	12.00
3	HEADLAMP RH <i>one -</i>	1.0	1,999.30	20	1,599.44
4	FRONT FENDER RH <i>rod/dys -</i>	1.0	421.10	20	336.88
5	FRONT FENDER SHIELD RH <i>rod/dys -</i>	1.0	112.30	20	89.84
6	FRONT FENDER PROTECTOR RH <i>dys -</i>	1.0	163.70	20	130.96
7	FRONT DOOR RH <i>sup -</i>	1.0	889.30	20	711.44
8	REAR DOOR RH <i>sup -</i>	1.0	935.10	20	748.08
9	REAR DOOR RH FRONT SIDE RUBBER <i>max</i>	1.0	40.10	20	32.08
10	REAR FENDER PROTECTOR RH <i>grand</i>	1.0	106.30	20	85.04
11	REAR DOOR TOP STICKER RH <i>net</i>	1.0	21.00	20	16.80
12	FRONT DOOR STICKER RH <i>net</i>	1.0	21.00	20	16.80
13	FRONT LOWER ARM RH <i>max</i>	1.0	312.20	20	249.76
14	FRONT WHEEL HUB BEARING RH <i>max</i>	1.0	138.00	20	110.40
15	FRONT SHOCK ABSORBER RH <i>max</i>	1.0	386.20	20	308.96
16	WING MIRROR ASSEMBLY <i>2 x</i>	1.0	606.60	20	485.28
17	FRONT WHEEL RIM RH <i>cut 450 s/w</i>	1.0	833.00	20	666.40
<b>List Price - Parts Sub Total</b>					<b>6,318.80</b>
18	REAR FENDER RH - REPAIR <i>2 x</i>	1.0			
19	FRONT TYRE RH <i>1 x</i>	1.0	380.00	0	380.00
<b>Special Nett Price - Parts Sub Total</b>					<b>380.00</b>
<b>Parts Total</b>					<b>6,698.80</b>
20	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,000.00	0	1,000.00
21	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,200.00	0	1,200.00
22	ANTI-RUST COATING	1.0	200.00	0	200.00
23	WIRING	1.0	40.00	0	40.00
24	TWO WHEEL ALIGNMENT	1.0	80.00	0	80.00
25	TO REMOVE & REFIT UNDERCARRIAGE	1.0	250.00	0	250.00
<b>Labour 1 Sub Total</b>					<b>2,770.00</b>

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

*P-4429-30  
 212  
 3543.44*

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

\* N = Item not subjected to GST

Issued by : Anysia

*1370  
 450  
 53634  
 4290*

# HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E  
 BEDOK NORTH AVE 4,  
 #01-2008/10/12 SINGAPORE 489977  
 TEL: 6441 5655 FAX: 6441 5355/6243 8121  
 R.O.C No: 200104141D GST Reg. No. 20-0104141-D

TO : 81823573  
 LOH KOH LIANG  
 NO

SINGAPORE  
 TEL : FAX :  
 PH : 81823573  
 ATTN :

## ESTIMATE BILL

Number : EB00006115  
 Date : 15/10/2022  
 Case No : AD00013190  
 Vehicle No : SKS3787M  
 Chassis: RU11017780  
 Year of Mfr 2015  
 Policy No  
 Model : HONDA VEZEL 1.5G  
 AUTO

**Term:**

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
	<div style="border: 1px solid blue; padding: 10px; width: fit-content; margin: auto;"> <p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts prices are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer                      Signature:                      Date:</p> </div>				
SINGAPORE DOLLARS : TEN THOUSAND ONE HUNDRED THIRTY-ONE AND CENTS SIXTY-TWO ONLY			<b>Less Excess</b>		0.00
			<b>SUBTOTAL</b>		9,468.80
			GST 7.00%		662.82
			<b>TOTAL</b>		<b>10,131.62</b>

Date of accident : 13/10/2022 05:45 PM. Place : NEW UPPER CHANGI ROAD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

\_\_\_\_\_  
 CUSTOMER SIGNATURE

\_\_\_\_\_  
 AUTHORISED SIGNATURE