

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22010272/KQY3Q2**Date:** 28/11/2022**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

Claimant Vehicle No : SLV4397X**Insured Vehicle No :** SMN6289S

Date of Loss: 07/10/2022

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLV4397X**

Make & Model: TOYOTA C-HR HYBRID, 1.8 S (A)

Engine No: 2ZR8250719

Reg. Date: 28/12/2017 (Man. Year: 2017)

Chassis No: ZYX102087417

Colour: Metallic Pearl White

Odometer: 346322 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60 R17

Front Left Side: Triangle 7 mm

Rear Left Side: Tourador 5 mm

Front Right Side: Triangle 7 mm

Rear Right Side: Tourador 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,711.02	829.95	881.07	51.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,070.00	420.00	650.00	60.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,781.02	1,249.95	1,531.07	55.05
Approved Total (Overridden) (S\$)		1,000.00		
Nett Amount (S\$)	2,781.02	1,000.00	1,781.02	64.04
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 17/10/2022

Date Inspected: 07/11/2022 Inspected At:

Lian Her Motors (Ang Mo Kio)
Blk 5038, Ang Mo Kio Industrial Park 2, #01-405
Singapore 569541

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Nov 2022)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV4397X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TOP BUMPER	Buckled	885.60 FL	*610.90 FL
2	1		*REAR LOWER BUMPER	Dented / Cut	455.70 FL	*455.70 FL
3	1		*REAR BUMPER REINFORCEMENT	Repair	483.20 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER	Serviceable	150.20 FL	*- FL
5	1		*REAR REVERSE SENSOR	Serviceable	200.00 FS	*- FS
6	15		*REAR BUMPER CLIP	No	30.00 FS	*30.00 FS
					Sub Total (\$\$)	2,204.70 1,096.60
					- List Item Discount on L Items 25.00/25.00% (\$\$)	493.68 266.65
					Total Parts (\$\$)	1,711.02 829.95

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING ,WELDING & CUTTING	New	500.00	200.00
2	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	550.00	220.00
3	CHECK AND RECONNECT WIRING	New	20.00	0.00
Gross Labour Cost (\$)			1,070.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >