

(08/11/13) Wef

ASS. REC. BY: Marcus

REF:

CS/HKA22010278/4943

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

C.C

Colour

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 3200

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

21/10/22 in hand MR lee 1/5 \$3200 (Red \$4186.94, 57%)

Not Authorized
 rer
 2/5 3200
 18/10/22
 4 days

T K LEE AUTOMOTIVE PTE. LTD

NO 1 KAKI BUKIT AVE 6 #02-47
 AUTOBAY SINGAPORE 417883
 Tel : 6509 5521 / 65095524 Fax : 6509 5523
 Email: Tklee0247@gmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Vehicle Number: GBH7056C

Vehicle Model: TOYOTA DYNA

Acknowledged by Repairer
 Signature:
 Date:

PARTICULAR

AMOUNT

QTY

SS

LIST PRICE

1	TAILGATE	20/3200	\$ 1,582.60	✓
1	TAILGATE STICKER 'TOYOTA'	rer	\$ 190.60	✓
1	TAILGATE STICKER 'DYNA'	11	\$ 58.60	X
1	TAILGATE LOWER MEMBER	3200	\$ 495.50	✓
4	TAILGATE HINGES @\$65.50	11	\$ 262.00	X
1	TAILGATE STOPPER -RH	7011	\$ 48.20	✓
1	TAILGATE STOPPER BRACKET -RH	3200	\$ 110.50	✓
1	TAILLAMP -RH	one	\$ 291.33	✓
1	TAILLAMP BRACKET	2	\$ 258.10	X
1	SIDEGATE -RH	PA	\$ 1,865.90	X
1	SIDEGATE LOCK HINGES -RH	3200	\$ 241.50	✓
1	SIDEGATE LOWER MEMBER	2	\$ 495.50	X
1	REAR EXHAUST PIPE	2	\$ 481.60	X
1	REAR LICENCE PLATE PANEL	3200	\$ 120.65	✓
			\$ 6,502.58	
LESS 25%			\$ 1,625.65	
			<u>\$ 4,876.94</u>	

SPECIAL NETT ITEMS

1	REAR NUMBER PLATE	3200	\$ 40.00	20
1	REAR STICKER '70KM/H'	rer	\$ 10.00	✓
1	REAR STICKER '13 PAX'	rer	\$ 10.00	✓
1	(SET) REAR REVERSE SENSOR	should	\$ 280.00	20
1	REAR STEP BRACKET	11	\$ 180.00	X
			<u>\$ 520.00</u>	

LABOUR CHARGES

TO CHECK REAR ELECTRICAL WIRING	\$ 50.00	20
TO REMOVE, REPLACE REVERSE SENSOR	\$ 60.00	40
TO TUFF KOTE	\$ 80.00	50
TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	\$ 900.00	550
TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	\$ 900.00	800
		<u>\$ 1,990.00</u>

ESTIMATE PARTS AND LABOUR GRAND TOTAL :

\$ 7,386.94

3080.88
 252
 2310.60
 4010.6