

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OO / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SMY 772R Yr Regn: 5/8/00  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Volkswagen Scirocco c.c. 1390  
 Colour: Green A/C: Insured / Std / Nil / NA  
 Sp. Reading 211578 T/Radio: Insured / Std / Nil / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WVWZ1Z137AYUSP758  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Mod: Nil / SIR / STD A/R / Im or \_\_\_\_\_  
 Tyre Size: F: 245/40R18  
 R: 1)

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Front Rear  
 R/Bal. 4 mm R/Bal. 4 mm  
 L/Bal. 4 mm L/Bal. 4 mm  
 D.O.A. 11/10/22 D.O.I. 18/10/22  
 Survey held at Sng Ah Tee  
 Des. of Damages: Frt / Rear / O/S NIS / UIC / Rooftop or  
& Front LH  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV-772R</u>

Order/Time, File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

1) \_\_\_\_\_  
 Date/Time, File Return to?

2) \_\_\_\_\_  
 Report Format: \_\_\_\_\_  
 Lump Sum / I.B.F. (\$) \_\_\_\_\_

Add Fee:  : Site Insp (\$) \_\_\_\_\_  
 : Interview (\$) \_\_\_\_\_  
 : Tech. Invs (\$) \_\_\_\_\_  
 : Weekend (\$) \_\_\_\_\_

Survey Fee:	_____
Transportation:	_____
\$ + RS. \$	_____
Photos	_____
Others	_____
TOTAL	_____

**Sng Ah Tee Motor & Panel Service Pte Ltd** (Co.Reg.No.200810440N)Blk 3 Pioneer Road North, #01-18  
Singapore 620457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER:

**Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2000944016-01	Date of Loss:	11/10/2022
Vehicle Reg. No.:	SMU772R	Driveable?	
Driver Age/Info:	27 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	MOHAMMAD TAUFIQ BIN ROSLI	Contact No:	+6592299426
Driver:	MOHAMMAD TAUFIQ BIN ROSLI		

Make/Model:	VOLKSWAGEN SCIROCCO, 1.4 L (A)	Vehicle Reg. Date:	02/08/2010
Vehicle Colour:	GREEN	Chassis No:	WVVZZZ13ZAV450758
Engine No:	CAV199257		
Odometer:	217578 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	20

Description of Accident/Loss	ON 11/10/2022 @
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	21,375.00
Miscellaneous Items	0.00
Labour	4,430.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$\$)</b>	<b>25,805.00</b>
<b>+ GST 7.00% (\$\$)</b>	<b>1,806.35</b>
<b>Nett Amount (\$\$)</b>	<b>27,611.35</b>

**This claim is handled by: JANICE CHANG SIEW YIN**

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

# DETAILS

Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Oct 2022)  
 144 VOLKSWAGEN SCIROCCO 1.4 L (A) (Catalogue Merimen Singapore 1.0)  
 Repairer's (Price-denominated Standard List)  
 At Code: (Unsubmitted, no print-code for SMU772R)  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER / BR ?	0.00	0.00	*700.00 F
2	2		*FRT BUMPER RETAINER	0.00	0.00	*80.00 F
3	10		*FRT BUMPER CLIPS / MK	0.00	0.00	*50.00 F
4	1		*FRT SIGNAL LAMP LH X	0.00	0.00	*90.00 F
5	2		*FRT SIGNAL LAMP COVER X	0.00	0.00	*120.00 F
6	2		*FRT FENDER / DD	0.00	0.00	*1,000.00 F
7	2		*FRT FENDER INNERSHIELD / Tn	0.00	0.00	*200.00 F
8	20		*FRT FENDER INNERSHIELD CLIPS / MK	0.00	0.00	*100.00 F
9	21		*FRT HEADLAMP (RH) / CV	0.00	0.00	*1,600.00 F
10	1		*FRT DOOR RH / DD	0.00	0.00	*1,200.00 F
11	1		*FRT DOOR LOCK RH	0.00	0.00	*250.00 F
12	1		*FRT DOOR OUTER HANDLE RH / CV	0.00	0.00	*180.00 F
13	1		*FRT DOOR OUTER HANDLE CAP RH / MS	0.00	0.00	*30.00 F
14	1		*FRT DOOR GLASS RH / BR	0.00	0.00	*200.00 F
15	1		*FRT DOOR GLASS REGULATOR RH	0.00	0.00	*220.00 F
16	1		*FRT DOOR GLASS REGULATOR MOTOR RH ?	0.00	0.00	*580.00 F
17	1		*FRT DOOR GLASS OUTER TOP MOULDING RH / CUT	0.00	0.00	*160.00 F
18	1		*FRT DOOR GLASS OUTER MOULDING RH / CV	0.00	0.00	*140.00 F
19	1		*FRT DOOR GLASS INNER MOULDING RH / CV	0.00	0.00	*170.00 F
20	1		*FRT DOOR GLASS UPPER INNER SEAL RH / MK	0.00	0.00	*180.00 F
21	1		*FRT DOOR GLASS LOWER INNER SEAL RH / MK	0.00	0.00	*120.00 F
22	1		*FRT DOOR INNER TRIM BOARD RH / Tn	0.00	0.00	*1,200.00 F
23	1		*FRT SIDE MIRROR ASSY RH / BR	0.00	0.00	*350.00 F
24	1		*FRT SIDE MIRROR COVER RH / MS	0.00	0.00	*150.00 F
25	1		*FRT SIDE MIRROR INNER SEAL RH / Tn	0.00	0.00	*120.00 F
26	1		*REAR FENDER RH / DD	0.00	0.00	*850.00 F
27	1		*REAR FENDER INNER SHIELD RH / Tn	0.00	0.00	*120.00 F
28	10		*REAR FENDER INNER SHIELD CLIPS / MK	0.00	0.00	*50.00 F
29	1		*REAR BUMPER / BR	0.00	0.00	*600.00 F
30	1		*REAR BUMPER RETAINER RH / BR	0.00	0.00	*35.00 F
31	10		*REAR BUMPER CLIPS / MK	0.00	0.00	*50.00 F
32	1		*REAR TAILLAMP RH / CV	0.00	0.00	*200.00 F
33	2		*FRT TYRE RIM / CV	0.00	0.00	*2,400.00 F
34	1		*REAR TYRE RIM RH / CV	0.00	0.00	*1,200.00 F
35	2		*FRT ABSORBER ?	0.00	0.00	*360.00 F
36	2		*FRT ABSORBER TOP MOUNTING ?	0.00	0.00	*170.00 F
37	2		*FRT KNUCKLE ARM ?	0.00	0.00	*1,000.00 F
38	2		*FRT WHEEL HUB & BEARING ?	0.00	0.00	*560.00 F
39	2		*FRT LOWER CONTROL ARM	0.00	0.00	*440.00 F
40	2		*FRT TIE ROD ?	0.00	0.00	*200.00 F
41	2		*FRT TIE ROD END ?	0.00	0.00	*240.00 F
42	1		*REAR QUARTER GLASS SEALANT / MK	0	0.00	*40.00 FS
43	2		*FRT DRIVESHAFT ?	0.00	0.00	*2,400.00 F
44	1		*FRT CROSSMEMBER ?	0.00	0.00	*850.00 F
45	1		*FRT ANTI ROLL BAR ?	0.00	0.00	*250.00 F

Report was unsubmitted during this print-out.  
 Generated using Merimen e-Claims IEAS

Part No.	Particulars	%Disc	%Depr	Amount
	*FRT STABILIZER LINK <sup>1</sup>	0.00	0.00	*170.00 F
Total Parts (S\$)				21,375.00

part. S=SpcNett.

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

es on Miscellaneous Items  
 new miscellaneous items selected.

Estimates on Labour  
 Particulars

Lab.Type Amount

Labour Items	Lab.Type	Amount
1 TO KNOCK, WELD, REMOVE & FIX ABOVE PARTS	New 1400	1,600.00
2 TO PUTTY & RESPRAY PAINTING ON AFFECTED AREA	New 1400	1,500.00
3 TO CHECK WIRING	New	50.00 ✓
4 TO TRANSFER FRT DOOR RH COMPONENTS	New	80.00 ✓
5 TO REMOVE & FIX REAR QUARTER GLASS	New ? 80	120.00
6 TO REPAIR & REPLACE UNDERCARRIAGE	New ? ?	750.00
7 TO REMOVE & REPLACE PETROL TANK	New	100.00
8 TO DO WHEEL ALIGNMENT	New	80.00 ✓
9 TO DIAGNOSE & RESET SYSTEM, CLEARING ERROR IN SYSTEM	New 100	150.00
<b>Gross Labour Cost (\$\$)</b>		<b>4,430.00</b>

Report was unsubmitted during this print-out.  
 Generated using Merimen e-Claims IEAS  
 < END OF ESTIMATES >

Steve (LKK)  
 18/10/22, 10:11  
 OO M AL  
 Excess - ?  
 LIS  
 My PL y  
 14 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**PARF/COE Rebate for Registered Vehicle**

**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC  
 Owner ID: 727J

**Vehicle Details**

Vehicle No.: SMU772R  
 Vehicle to be Exported: No  
 Intended Deregistration Date: 19 Oct 2022  
 Vehicle Make: VOLKSWAGEN  
 Vehicle Model: SCIROCCO 1.4L AT TSI 1372Q5  
 Primary Colour: White  
 Manufacturing Year: 2010  
 Engine No.: CAV199257  
 Chassis No.: WVVZZZ13ZAV450758  
 Maximum Power Output: 118.0 kW (158 bhp)  
 Open Market Value: \$23,903.00  
 Original Registration Date: 05 Aug 2010  
 First Registration Date: 05 Aug 2010  
 Transfer Count: 4  
 Actual ARF Paid: \$23,903.00

**Intended PARF Rebate Details**

PARF Eligibility: Forfeited  
 PARF Eligibility Expiry Date: -  
 PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 04 Aug 2030  
 COE Category: A - Car (1600cc & below)  
 COE Period(Years): 10  
 PQP Paid: \$32,190.00  
 COE Rebate Amount: \$25,085.00  
**Total Rebate Amount: \$25,085.00**

The information contained herein is correct as at 12 Oct 2022

OK