



Your Ref : IVS22/1688

Date: 11<sup>th</sup> Nov 2022

Our Ref : CS/LIP22010285/Nwy3e2

**M/s Liberty Insurance Pte Ltd**

51 Club Street, #03-00

Liberty House

Singapore 069428

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMA 373P  
ACCIDENT ON 01/10/2022**

Instruction was received to inspect the vehicle Reg. No. SMA 373P. The inspection was conducted on 20/10/2022 at the premises of M/s Performance Motors Ltd, 303 Alexandra Road, Singapore 159941.

The following vehicle information was recorded:

Registration Number	: SMA 373P
Make/Model	: B.M.W. 216D Active Tourer LED EU6
Registration Date	: 26 Apr 2018
Body Colour	: Grey
Chassis Number	: WBA2B32020V926398
Engine Capacity	: 1496 cc

The vehicle sustained damages at the front portion, o/s, n/s body, undercarriage and rooftop. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 95,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 41,739.00
Nett Liability	<u>S\$ 53,261.00</u> =====

Vehicle Inspected By:



MUHD NAZRIL (NAZ)  
Technical Investigator  
LL.B. (Hons) London



K.K.LAU  
MSc(Eng M), B Eng(Hons), PEng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.