

Vehicle Damage Assessment Report for [SKT8610B]

Estimate Created: 15/12/2022 23:56 by Insurlogic 1 (Insurlogic_Pte_Ltd)

Owned: 16/12/2022 00:10 by Insurlogic 1 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO INSURANCE	Claim Number
Claim Type	OD	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	BMW	Model	5-Series
Engine Type			
License Plate Number	SKT8610B	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at \$18,002.90 with 5 days for repair

Insurlogic 1 (16/12/2022 00:10)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
BONNET		1	2378.95	0.00 %	2,378.95
FRONT SHOCK ABSORBER		1	72.50	0.00 %	72.50
FRONT BUMPER PANEL		1	1424.20	0.00 %	1,424.20
SUPPORT		1	4.90	0.00 %	4.90
FRONT RH GRILLE		1	144.35	0.00 %	144.35
BMW EMBLEM		1	72.85	0.00 %	72.85
RH HEADLAMP SUPPORT		1	225.20	0.00 %	225.20
AIR DUCT		1	409.50	0.00 %	409.50
RH BI XENON HEADLIGHT		1	2702.85	0.00 %	2,702.85
CONDENSER AIRCON		1	1086.35	0.00 %	1,086.35
BLIND RIVET FLAT HEADED		1	18.00	0.00 %	18.00
FRONT RH 1 SIDE PANEL BRACKET		1	41.20	0.00 %	41.20
FRONT BUMPER CARRIER		1	722.70	0.00 %	722.70
RH LEVER		1	6.95	0.00 %	6.95
BUMPER RIVET		1	5.00	0.00 %	5.00
FRONT RH LOCATOR SEAL		1	232.00	0.00 %	232.00
REPAIR KIT SOCKET		1	16.50	0.00 %	16.50
SET GASKET		1	50.90	0.00 %	50.90
NOTICE SAFETY CATCH		1	25.00	0.00 %	25.00
LABEL COOLANT		1	25.00	0.00 %	25.00
SUNDRIES		1	150.00	0.00 %	150.00

Parts Subtotal 9,814.90

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
EMBOSS NUMBER PLATE		1.0	83.00	0.00 %	83.00

Materials Subtotal 83.00

Labor

Description	Type	Cost	Markup/Disc %	Price
REPLACE/ REPAIR ACCIDENT AFFECTED ITEMS AND AREAS	RnR	2550.00	0.00 %	2,550.00
RNR PDC SENSOR	RnR	168.00	0.00 %	168.00
CHECK ELECTRICAL	RnR	168.00	0.00 %	168.00
REPLACE HEADLAMP RH	RnR	456.00	0.00 %	456.00
RNR RADIATOR ASSY	RnR	639.00	0.00 %	639.00
RNR AIRCON CONDENSER AND REFILL GAS	RnR	953.00	0.00 %	953.00
BODY CAVITY	RnR	112.00	0.00 %	112.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
PAINT ON ACCIDENT AFFECTED AREAS	Full spray	3059.00	0.00 %	3,059.00

General Labor Subtotal 5,046.00

Paint Labor Subtotal 3,059.00

Labor Subtotal 8,105.00

Summary

Repair Cost 18,002.90

Discount(0 %) (0.00)

18,002.90

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 18,002.90