

Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



car in since 13/10
key press room level 6.
survey repair

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 63693
Date Estimated : 14/10/2022
Prepared By : Yap Mee Key

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Lim Kim Mooi
33 Ingg Road

Singapore 757195

- ACCOUNT - 136

Ergo Insurance Pte Ltd
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKT8610B	WBA5A52070D823656	29/05/2015	5281A	153850

DESCRIPTION	VALUE
To replace bonnet, front support, front bumper, make good front rhs fender and attachments. 3 x 850	2550 3,825.00
To respray bonnet, front bumper, front rhs fender and affected areas.	3059 3,221.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168 177.00
To check electrical.	168 177.00
To supply front emboss number plate.	83.00
To replace right headlamp.	456 481.00
To replace radiator assembly, fan housing with fan including pressure test, bleed cooling system and conduct check for leak. (All models except 7 series).	7 826.00
To replace air con condenser and air con hose including vacuum system, top up freon gas and conduct check for leak. (For all models except for 7 series).	7 1,003.00
Sundries.	80.00

Total Labour 1: 9,873.00

DESCRIPTION	QTY	PRIC	VALUE
RADIATOR UPPER SEALING	1	34.80	34.80
Radiator	1	836.85	836.85
BONNET	1	1,312.90	1,312.90
FRT BUMPER TOP CARRIER	1	419.45	419.45
Open grid, r	1	76.95	76.95
LH FINISHER ROD (BASIS)	1	33.55	33.55



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Page No. : 2 of 5

Estimate No. : b1 63693
 Date Estimated : 14/10/2022
 Prepared By : Yap Mee Key

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKT8610B	WBA5A52070D823656	29/05/2015	528ia	153850

DESCRIPTION	QTY	PRIC	VALUE
RH FINISHER ROD (BASIS)	1	33.55	33.55
BRACKET HEADLIGHT RH	1	15.00	15.00
SUPPORT CENTRAL	1	14.15	14.15
MOUNTING SUPPORT	1	15.75	15.75
Panel (Bump - R)	1	1,106.35	1,106.35
FLAP TOWING EYE PRIMED	1	44.35	44.35
Grille, fron (RH)	1	131.20	131.20
Grille, fron (LH)	1	131.20	131.20
FRONT PANEL V STRUT	1	120.75	120.75
SUPPORT RH	1	129.25	129.25
C CLIP NUT	10	1.35	13.50
AIR DUCT RADIATOR	1	189.40	189.40
PLAQUE 82MM	1	72.85	72.85
Headlight (RH)	1	1,109.95	1,109.95
Condenser ai	1	1,034.65	1,034.65
Total Parts :			6,876.40

Steve (LKK)
 17/10/22, 5.00pm
 OP. M AL
 Excess - ?
 P/P
 my BL y
 S dy

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- subject to confirmation
- is on a "Without Prejudice" basis
- ation(s) is allowed
- an(s) must be resurveyed and
- approval from Insurance Company



Acknowledged by Repairer

Labour 1	:	9,873.00
Parts	:	6,876.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,172.46
Grand Total	:	17,921.86

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **