



Supplementary

Estimate No. : **b1 63776**
 Date Estimated : **21/10/2022**
 Prepared By : **Yap Mee Key**

Page No. :

- ESTIMATE REPAIR FOR -

Lim Kim Mooi
33 Ingg Road

Singapore 757195

- ACCOUNT - 136

Ergo Insurance Pte Ltd
8 Temasek Boulevard
#04-01 Suntec Tower 3
Singapore 038988

REGN. NO.	CHASSI S NO.	REGN. DATE	MODEL	M LEAGE
SKT8610B	WBA5A52070D823656	29/05/2015	528iA	153850

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
* To remove and install radiator assembly to facilitate repairs include conducting pressure tests, bleed cooling system and checks for leak	639.00		639.00 ✓
* To replace air con condenser and air con hose including vacuum system, top up freon gas and conduct checks for leak	953.00		953.00 ✓
* To carry out body cavity preservation	112.00		112.00 ✓
* Sundries.	150.00		150.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT	
# BLIND RIVET FLAT HEADED 6.5X14.3	4.50	4.00	0.00	18.00 ✓	NEC
# FRT RH 1 SIDE PANEL BRACKET	41.20	1.00	0.00	41.20 ✓	BT
# FRT BUMPER CARRIER	722.70	1.00	0.00	722.70 ✓	BT
# RH LEVER	6.95	1.00	0.00	6.95 ✓	MIS
# BUMPER RIVET	0.50	10.00	0.00	5.00 ✓	NEC
# FRT RH LOCATOR SEAL	232.00	1.00	0.00	232.00 ✓	BR
# REPAIR KIT SOCKET HOUSING (12 POL)	16.50	1.00	0.00	16.50 ✓	NEC
# GASKET SET	50.90	1.00	0.00	50.90 ✓	NEC
# NOTICE SAFETY CATCH	25.00	1.00	0.00	25.00 ✓	NEC
# LABEL COOLANT	25.00	1.00	0.00	25.00 ✓	NEC

SUPPLEMENTARY ITEMS

Total Labour :	1,854.00
Total Parts :	1,143.25
Total Labour & Parts :	2,997.25

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
 Co Reg No. 197401559W

