



Final Report

Estimate No. : **b1 63776**
 Date Estimated : **21/10/2022**
 Prepared By : **Yap Mee Key**

Page No. :

- ESTIMATE REPAIR FOR -

Lim Kim Mooi
33 Ingg Road

Singapore 757195

- ACCOUNT - 136

Ergo Insurance Pte Ltd
8 Temasek Boulevard
#04-01 Suntec Tower 3
Singapore 038988

REGN. NO.	CHASSI S NO.	REGN. DATE	MODEL	M LEAGE
SKT8610B	WBA5A52070D823656	29/05/2015	528iA	153850

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachments, bonnet, front air duct, RH headlamp support, front RH locator seal, front RH side panel bracket include making good the front RH fender and knocking out dents caused by the accident	2,550.00		2,550.00
To spray paint bonnet, front bumper and front RH fender	3,059.00		3,059.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function	168.00		168.00
To check electrical wiring system at the front section for proper function	168.00		168.00
To replace RH high intensity headlight include functionality programming and conducting checks for proper function	456.00		456.00
* To remove and install radiator assembly to facilitate repairs include conducting pressure tests, bleed cooling system and checks for leak	639.00		639.00
* To replace air con condenser and air con hose including vacuum system, top up freon gas and conduct checks for leak	953.00		953.00
* To carry out body cavity preservation	112.00		112.00
To supply front emboss number plate.	83.00		83.00
* Sundries.	150.00		150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET FLAT HEADED 6.5X14.3	4.50	4.00	0.00	18.00
# FRT RH 1 SIDE PANEL BRACKET	41.20	1.00	0.00	41.20

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
 Co Reg No. 197401559W





Final Report

BONNET	2,378.95	1.00	0.00	2,378.95
# FRT BUMPER CARRIER	722.70	1.00	0.00	722.70
SUPPORT	4.90	1.00	0.00	4.90
FRT SHOCK ABSORBER	72.50	1.00	0.00	72.50
# RH LEVER	6.95	1.00	0.00	6.95
FRT BUMPER PANEL PRIMED (PDC)	1,424.20	1.00	0.00	1,424.20
# BUMPER RIVET	0.50	10.00	0.00	5.00
FRT RH GRILLE (BASIS)	144.35	1.00	0.00	144.35
BMW EMBLEM	72.85	1.00	0.00	72.85
RH HEADLAMP SUPPORT	225.20	1.00	0.00	225.20
AIR DUCT	409.50	1.00	0.00	409.50
# FRT RH LOCATOR SEAL	232.00	1.00	0.00	232.00
# REPAIR KIT SOCKET HOUSING (12 POL)	16.50	1.00	0.00	16.50
RH BI XENON HEADLIGHT	2,702.85	1.00	0.00	2,702.85
# GASKET SET	50.90	1.00	0.00	50.90
CONDENSER AIR CONDITIONING	1,086.35	1.00	0.00	1,086.35
# NOTICE SAFETY CATCH	25.00	1.00	0.00	25.00
# LABEL COOLANT	25.00	1.00	0.00	25.00

SUPPLEMENTARY ITEMS

Total Labour :	8,338.00
Total Parts :	9,664.90
Total Labour & Parts :	18,002.90
Deduction for Excess :	700.00
Total Repair Costs less Excess:	17,302.90
GST @7%:	1,211.20
Grand Total :	18,514.10

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

