

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22010292/DNY3E2**Date:** 11/01/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001895928
Claimant Vehicle No :	SNG1051T	Insured Vehicle No :	SGS32A
Date of Loss:	13/10/2022	Nature of Claim:	TP
		Claim No:	287907

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNG1051T		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK062820
Reg. Date:	11/07/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF42JA178321
Colour:	Black	Odometer:	70723 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,148.70	6,352.20	13,796.50	68.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,020.00	1,540.00	1,480.00	49.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,168.70	7,892.20	15,276.50	65.94
Approved Total (Overridden) (S\$)		6,300.00		
(S\$)	23,168.70	6,300.00	16,868.70	72.81
+ GST 8.00/8.00% (S\$)	1,853.50	504.00	1,349.50	72.81
Nett Amount (S\$)	25,022.20	6,804.00	18,218.20	72.81

INSPECTION

Date of Assignment:	19/10/2022	
Date Inspected:	18/10/2022 Inspected At:	C.S. Ong Auto Pte Ltd (AMK) 10 Ang Mo Kio Industrial Park 2A, #02-16, AMK Auto Point Singapore 568047
Estimated Period of Repair:	6.0 days	

Adjuster: BRYAN TANI**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jan 2023)
Parts:	143	AUDI A4 2.0 SEDAN TFSI S-TRONIC (NAV) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNG1051T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Dented	1,850.00 FL	*981.60 FL
2	1		*FRONT FENDER INNER SHIELD LH	Serviceable	201.00 FL	*- FL
3	1		*FRONT BUMPER	Distorted	2,493.00 FL	*1,901.60 FL
4	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	192.00 FL	*- FL
5	1		*FRONT SHOCK ABSORBER LH	Not Necessary	637.00 FL	*- FL
6	1		*FRONT LOWER ARM LH	Not Necessary	1,057.00 FL	*- FL
7	1		*FRONT KNUCKLE ARM LH	Not Necessary	1,270.00 FL	*- FL
8	1		*FRONT KNUCKLE ARM BEARING LH	Not Necessary	438.00 FL	*- FL
9	1		*FRONT WHEEL BEARING HUB LH	Not Necessary	372.00 FL	*- FL
10	1		*FRONT CONTROL ARM LH	Not Necessary	564.00 FL	*- FL
11	1		*FRONT TRAILING ARM LH	Not Necessary	631.00 FL	*- FL
12	1		*FRONT UPPER ARM LH	Not Necessary	573.00 FL	*- FL
13	1		*FRONT DOOR LH	Dented	3,821.00 FL	*2,744.80 FL
14	1		*FRONT DOOR WINDOW MOULDING LH	Not Necessary	210.00 FL	*- FL
15	1		*FRONT DOOR BLACK STICKER LH	Necessary	194.00 FL	*80.00 FL
16	1		*FRONT DOOR LOCK LH	Not Necessary	432.00 FL	*- FL
17	1		*FRONT DOOR WEATHER STRIP OUTER LH	Not Necessary	480.00 FL	*- FL
18	1		*FRONT DOOR INNER TRIM BOARD LH	Not Necessary	1,692.00 FL	*- FL
19	1		*FRONT DOOR WINDOW MOTOR LH	Not Necessary	1,149.00 FL	*- FL
20	1		*FRONT DOOR WINDOW REGULATOR LH	Not Necessary	690.00 FL	*- FL
21	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
22	1		*FRONT DOOR INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
23	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*15.00 FS
24	1		*FRONT RIM LH	Distorted / Cracked	2,000.00 FS	*1,200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	21,096.00	6,923.00
- List Item Discount on L Items 5.00/10.00% (\$)	947.30	570.80
Total Parts (\$)	20,148.70	6,352.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	900.00	700.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	1,200.00	700.00
3	TO CONDUCT WHEEL ALIGNMENT TEST	New	150.00	60.00
4	TO REMOVE AND RENEW FRONT UNDERCARRIAGE	New	250.00	0.00
5	TO TUFF COAT DAMAGED AREAS	New	200.00	20.00
6	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	New	120.00	60.00
7	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
Gross Labour Cost (S\$)			3,020.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >