

C. S. ONG AUTO PTE LTD

Co. Reg. No.: 201408916W

7030, ANG MO KIO AVE 5, #B1-01 NORTHSTAR @ AMK, SINGAPORE 569880

TEL: 6484 1933 | FAX: 6481 1916

E-Mail: csongauto.claims@yahoo.com.sg

To: MSIG

Att: Motor Claims Dept

ACCIDENT INVOLVING SGS32A [YOUR INSURED] & SNG1051T [OUR CLIENT]
ON 17/10/2022.

ESTIMATED REPAIR COSTS FOR SNG1051T

MODEL : AUDI A4

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	FRONT FENDER LH <i>Damage</i>	981.60	\$ 1,850.00 ✓
1PC	FRONT FENDER INNER SHIELD LH <i>Scr</i>		\$ 201.00 X
1PC	FRONT BUMPER <i>crushed</i>	1901.60	\$ 2,493.00 ✓
1PC	FRONT BUMPER SIDE RETAINER LH <i>Scr</i>		\$ 192.00 X
1PC	FRONT SHOCK ABSORBER LH <i>HH</i>		\$ 637.00 X
1PC	FRONT LOWER ARM LH <i>HH</i>		\$ 1,057.00 X
1PC	FRONT KNUCKLE ARM LH <i>HH</i>		\$ 1,270.00 X
1PC	FRONT KNUCKLE ARM BEARING LH <i>HH</i>		\$ 438.00 X
1PC	FRONT WHEEL BEARING HUB LH <i>HH</i>		\$ 372.00 X
1PC	FRONT CONTROL ARM LH <i>HH</i>		\$ 564.00 X
1PC	FRONT TRAILING ARM LH <i>HH</i>		\$ 631.00 X
1PC	FRONT UPPER ARM LH <i>HH</i>		\$ 573.00 X
1PC	FRONT DOOR LH <i>Damage</i>	2744.80	\$ 3,821.00 ✓
1PC	FRONT DOOR WINDOW MOULDING LH <i>HH</i>		\$ 210.00 X
1PC	FRONT DOOR BLACK STICKER LH <i>HH</i>	80.00	\$ 194.00 ✓
1PC	FRONT DOOR LOCK LH <i>HH</i>		\$ 432.00 X
1PC	FRONT DOOR WEATHER STRIP OUTER LH <i>HH</i>		\$ 480.00 X
1PC	FRONT DOOR INNER TRIM BOARD LH <i>HH</i>		\$ 1,692.00 X
1PC	FRONT DOOR WINDOW MOTOR LH <i>HH</i>		\$ 1,149.00 X
1PC	FRONT DOOR WINDOW REGULATOR LH <i>HH</i>		\$ 690.00 X
		PARTS SUM:	\$ 18,946.00
		PARTS LESS 5%:	\$ 947.30
		PARTS TOTAL:	\$ 17,998.70

5708.00
10% 5,137.20

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY FRONT FENDER INNER SHIELD CLIPS <i>HH</i>	\$ 50.00	X
*	TO SUPPLY FRONT DOOR INNER TRIM CLIPS <i>HH</i>	\$ 50.00	X

*	TO SUPPLY FRONT BUMPER CLIPS Hec	\$ 50.00	15/-
*	TO SUPPLY FRONT RIM LH custom 1 crack	\$ 2,000.00	1200/-
		1215.00	
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 900.00	700/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 1,200.00	700/-
*	TO CONDUCT WHEEL ALIGNMENT TEST	\$ 150.00	60/-
*	TO REMOVE AND RENEW FRONT UNDERCARRIAGE	\$ 250.00	H4
*	TO TUFF COAT DAMAGED AREAS	\$ 200.00	20/-
		1540.00	
*	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	\$ 120.00	60/-
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00	H4

LABOUR & S/N TOTAL: \$ 5,170.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 23,168.70

18/10/2022 @ 1645hr

Not Audu

2/sum

1 ryan 6 days.

LKK Auto

8

Check part prices.

7892.20

4/5 6,300/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: