

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 10 Jan 2023

Preliminary Advice

Insured Vehicle No	: SGS32A	Accident Date	: 13/10/2022
TP Vehicle No	: SNG1051T	Assignment Date	: 19/10/2022
Make	: AUDI A4	Est. Duration of Repair	: 6
Date of Inspection	: 18/10/2022		
Inspection At	: C.S. ONG AUTO PTE LTD (AMK) 10 ANG MO KIO INDUSTRIAL PARK 2A, #02-16, AMK AUTO POINT SINGAPORE 568047		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,168.70
Revised Amount	:S\$	7,892.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,892.20
 Lump Sum Repair	 :S\$	 6,300.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (x) Lump Sum repair
- (x) The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.