



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:KITTY		Ref: CC4/ASM22010297/Upa3q2 Date: 04/05/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHC 7589L	Veh. Inspected	SNE 3533S
Policy No.	P2465703	Coverage (\$)	0.00
Claim No.	S2M04CRU	Excess (\$)	0.00
Assign From		Assign Date	17/10/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	mitsubishi space star (A)	c.c	1193
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MMCXTA03AGH035504	Colour	SILVER
Odometer	52722 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	175/55 R15	BRIDGESTONE	6 mm
L/H Front Tyre	175/55 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	175/55 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	175/55 R15	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	12/10/2022	Inspection Date	18/10/2022
Survey held at	SOON SAN MOTOR TRADING BLK 3006 UBI ROAD 1 #01-390 SINGAPORE 408716		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	