

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

Email: soonosanmotor@gmail.com

To: Motor Claims Dept

AXA INSURANCE SINGAPORE PTE LTD

8, Shenton Way #27-01

AXA Tower

S,pore 068811

Accident date:12/10/2022

Date:13/10/2022

- LKK Auto Consultants herice notify
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Arthur
18/10/22
L/S \$3400/
5 days
wh/pt. Att-ry-
w/cons

Estimate cost to repair vel: SNE 3533S (Mitsubishi space star) claims under vel: SHC 7589L.

1pce tail gate	\$ 913.00	2 x
1pce tail gate windscreen rubber	164.00	1 x
1pce tail gate windscreen inner sealant	120.00	1 x
1pce tail gate windscreen tape form	50.00	1 x
1pce tail gate emblem	45.00	1 x
1pce tail gate cc plate	25.00	1 x
1pce tail gate mivce plate	70.00	1 x
1pce tail gate space star plate	58.00	1 x
1pce tail gate windscreen sunx sticker	300.00	1 x
2pcs tail lamp@\$481	962.00	CPA ✓
1pce rear bumper	684.00	Turn ✓
2pcs rear bumper reflector@\$40	80.00	1 x
1set rear bumper reverse sensors	350.00	swk 200 S/N
2pcs rear bumper inner brackets@\$45	90.00	3x ✓
10pcs rear bumper inner clips@\$5	50.00	1x ✓
2pcs rear bumper side holders@\$30	60.00	1x ✓
1pce rear panel	428.00	Body ID ✓
1pce rear panel lower lock cover	120.00	Tw ✓
1pce rear exhaust pipe	835.00	1 x
To rustproof	200.00	30
To remove/refit rear windscreen	140.00	1 x
To remove/refit rear exhaust pipe	100.00	1 x
To remove/refit rear interior to effect repair	100.00	80
To dismantle/renew accident portion	1,200.00	900

To spray paint

1,200.00
TOTAL: \$8,344.00

1-2394
102
2154.60
200
1910
4264.6
3411