

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 4451A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	PANEL ASSY -REAR DOOR RH (CONSISTENT)	BENT	2,147.90	2,147.90
1	MOULDING ASSY W/LINE RR D (CONSISTENT)	CUT	125.30	125.30
1	CAP ASSY -WHEEL HUB(CONSISTENT)	CUT	346.40	346.40
	LESS 20% DISCOUNT		-523.92	-523.92
			2,095.68	2,095.68
	SPECIAL NETT ITEMS			
1	ZIG BOOK NOW APP LOGO REA (SN)(CONSISTENT)	CUT	80.00	80.00
			80.00	80.00
	<u>LABOUR</u>			
	PANEL BEATING.		800.00	525.00
	SPRAYPAINT CHARGE.		1,000.00	600.00
	REMOVE/REFIX UPHOLSTERY REAR .		100.00	60.00
	TRANSFER DOOR PARTS.		120.00	60.00
			2,020.00	1,245.00
	GRAND TOTAL		4,195.68	3,420.68

RECOMMENDED COST OF REPAIRS			3,420.68
-----------------------------	--	--	----------

Report Ref No. CC4/ASM22010304/Tpa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

HO LEONG CHUAN

Automotive Assessor

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.