



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TP/DS

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM	<i>liability check</i>		S1000020 / TPCLAIM		Mr Tan Pei Ling		
			Document No.		53G Holland Road		
			0		Singapore 258863		
			Document Date		Mobile: 97579455		
		14/10/2022					

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	AYH30R	PFXQB H6	24/08/2021	SNB4490R	0	22108	69DS/SNB4490R

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTNHS3DH308056056	2AR2705597	60	Raymond Seah L M	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI SUNDRIES TP VEH:SHD6368J ACC DATE:14/10/2022 TP INS: NO OF REPAIR DAYS: DATE-IN: DATE SURVEY: BY: AUTHORISED ON: -TP/DS CLAIM				30.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR FRONT AND REAR DOOR				120.00
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
4	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.				122.40
5	B	BP-LAB2 TO TRANSFER BOTH FRONT AND REAR DOOR BOARD.GLASS,MOTOR,REGULATOR AND OTHER ATTACHMENT TO FACILIATE REPAIRS.				720.00
6	B	BP-LAB2 TO REPLACE RH SIDE ACCIDENT DAMAGE PARTS.STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.				3600.00
7	B	BP-RES2 TO SPRAY PAINT ON RH SIDE ACCIDENT AFFECTED AREAS.				3540.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Mr Tan Pei Ling 53G Holland Road Singapore 258863 Mobile: 97579455		
			Document No. 0				
			Document Date 14/10/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	AYH30R	PFXQB H6	24/08/2021	SNB4490R	0	22108	69DS/SNB4490R
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTNHS3DH308056056		2AR2705597	60	Raymond Seah L M	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
8	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION				366.36	
9	1	T67001-58070 PANEL SUB-ASSY, FR	1.00	2251.30		2251.30	
10	2	T75921-58010 TAPE, BLACK OUT,	1.00	23.70		23.70	
11	3	T75923-58010 TAPE, BLACK OUT,	1.00	42.50		42.50	
12	4	T75751-58011 MOULDING, FR DOOR	1.00	46.90		46.90	
13	5	T75753-58010 MOULDING, FR DOOR	1.00	107.40		107.40	
14	6	L90269-04051 RIVET	1.00	1.70		1.70	
15	7	T76903-58050 C0 MUDGUARD SUB-ASSY,	1.00	873.70		873.70	
16	8	T67003-58110 PANEL SUB-ASSY,	1.00	2856.80		2856.80	
17	9	T75741-58030 MOULDING, RR DOOR,	1.00	149.30		149.30	
18	0	T76905-58050 C0 MUDGUARD SUB-ASSY,	1.00	811.30		811.30	
19	1	T76907-58080 C0 MUDGUARD SUB-ASSY,	1.00	323.30		323.30	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 16,166.66
			Please acknowledge receipt of vehicle		Parts 7,487.90		GST 7.00% 1,131.67
					Labour 8,312.40		Less 0.00
					Sublet 366.36		
					Lubrication/Fluid 0.00		
					Others 0.00		Amount Due 17,298.33

Customer Copy