

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LIBERTY INSURAI	NCE PTE LTD	Ref:	CS/LIP22010312/Uqy3m4	
	51 CLUB STREET, LIBERTY HOUSES	, #03-00 SINGAPORE 069428	Date:	28/10/2022	
			Code:	LIP	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SNC 9920D	Veh. Inspected	SME 5616K	
	Policy No.	SD21V17243/VPL/R00	Coverage (\$)	0.00	
	Claim No.	AVS22/2821	Excess (\$)	0.00	
	Assign From	TED SEAH	Assign Date	17/10/2022	
2.	. Vehicle Particulars & Condition				
	Make & Model	HONDA CIVIC (A)	c.c	1597	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	MRHFC5650JT001509	Colour	GREY	
	Odometer	51360 KM	Steering	AFFECTED	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	215/55 ZR16	DUNLOP	7 mm	
	L/H Front Tyre	215/55 ZR16	DUNLOP	7 mm	
	R/H Rear Tyre	215/55 ZR16	DUNLOP	7 mm	
	L/H Rear Tyre	215/55 ZR16	DUNLOP	7 mm	
4.	1. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	05/10/2022	Inspection Date	18/10/2022	
	Survey held at	2ND AUTO PTE LTD			
		15 KAKI BUKIT ROAD 4, #01-53, BARTLEY BIZ CENTRE, SINGAPORE 417808			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				