

Case Details

Case Reference Number : TAX/10/22/2060
Type of Repair : Accident Repair
Vehicle Registration Number : SHB5931A

Company Type : Strides Taxi Pte Ltd
Estimation ID : EST-19641-ID
Assigned By : Tan Lee Ge #

Insurance Company Name : AXA Insurance Singapore Pte Ltd
Accident Date and Time : 17/10/2022 08:20 PM
Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Quantity	Surveyor Approval		Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)			Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			APRON SUB-ASSY, FRONT FENDER, LH	1	1,060.80	1,060.90	30.00	742.63	Replace	0	0	Check	?
One Time Key In	Main			SHAFT ASSY, FRONT DRIVE, LH	1	1,355.80	1,355.80	30.00	949.06	Replace	0	0	Check	?
One Time Key In	Main			OIL SEAL, FRONT DRIVE SHAFT, LH	1	39.20	39.20	30.00	27.44	Replace	0	0	Check	?
One Time Key In	Main			END SET, TIE ROD, LH	1	202.30	202.30	30.00	141.61	Replace	0	0	Check	?
One Time Key In	Main			LINK ASSY, FRONT STABILIZER, RH & LH	1	256.40	256.40	30.00	179.48	Replace	0	0	Check	?
One Time Key In	Main			JOINT ASSY, LWR BALL, RH & LH	1	284.50	284.50	30.00	199.15	Replace	0	0	Check	?
One Time Key In	Main			BAR, STABILIZER, FR	1	382.60	382.60	30.00	267.82	Replace	0	0	Check	?
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL, LH	1	649.10	649.10	30.00	454.37	Replace	1	0.00	Replace	der
One Time Key In	Main			FRONT CROSSMEMBER	1	2,795.70	2,795.70	30.00	1,956.99	Replace	0	0	Check	?
One Time Key In	Main			FRONT REINFORCEMENT SIDE LH	1	144.30	144.30	30.00	101.01	Replace	0	0	Check	?
One Time Key In	Main			TRANSAXLE ASSY, HYBRID VEHICLE	1	12,528.50	12,528.50	10.00	11,275.65	Replace	0	0	Not Give	XAN
One Time Key In	Main			GEAR ASSY, STEERING	1	2,115.80	2,115.80	30.00	1,481.06	Replace	0	0	Check	?
Standard	Main			COVER, FR BUMPER	1	565.60	565.60	30.00	395.92	Replace	1	395.92	Replace	TAN

Total Spare Part Cost 48,888.92

Surveyor Total 8,330.94

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 48,888.92

Final Sur Total 8,330.94

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			SUPPORT, FR BUMPER LH	1	86.20	86.20	30.00	60.34	Replace	1	60.34	Replace	car
Standard	Main			COVER, FR BUMPER LH	1	32.70	32.70	30.00	22.89	Replace	0	0	Not Give	X11
Standard	Main			GRILLE, RADIATOR	1	192.80	192.80	30.00	134.96	Replace	0	0	Not Give	X11
Standard	Main			GRILLE SUB-ASSY	1	457.10	457.10	30.00	319.97	Replace	0	0	Not Give	X11
Standard	Main			GRILLE, SUB - ASSY, 2	1	170.20	170.20	30.00	119.14	Replace	0	0	Not Give	X11
Standard	Main			COVER ASSY, ENGINE	1	261.60	261.60	30.00	183.12	Replace	1	183.12	Replace	car
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.80	48.00	30.00	33.60	Replace	10	33.60	Replace	car
Standard	Main			RETAINER, FR BUMPER, LH & RH	1	9.50	9.50	30.00	6.65	Replace	1	6.65	Replace	car
Standard	Main			MOULDING, FRONT BUMPER SIDE, LH	1	103.70	103.70	30.00	72.59	Replace	1	72.59	Replace	car
Standard	Main			PAD, FRONT BUMPER (NO.1)	1	44.10	44.10	30.00	30.87	Replace	0	0	Not Give	X11
Standard	Main			PAD, FRONT BUMPER (NO.2)	1	38.90	38.90	30.00	27.23	Replace	0	0	Not Give	X11
Standard	Main			ABSORBER, FR BUMPER LOWER	1	143.60	143.60	30.00	100.52	Replace	0	0	Not Give	X11
Standard	Main			ABSORBER, FR BUMPER	1	86.60	86.60	30.00	60.62	Replace	0	0	Not Give	X11
Standard	Main			EXTENSION SUB-ASSY, RH	1	129.90	129.90	30.00	90.93	Replace	0	0	Not Give	X11
Standard	Main			EXTENSION SUB-ASSY, LH	1	129.90	129.90	30.00	90.93	Replace	0	0	Not Give	X11
Standard	Main			REINFORCEMENT FRONT LOWER	1	265.90	265.90	30.00	186.13	Replace	0	0	Not Give	X11
Standard	Main			REINFORCEMENT FRONT UPPER	1	773.90	773.90	30.00	541.73	Replace	0	0	Not Give	X11
Standard	Main			UNIT, HEADLAMP, LH	1	2,852.40	2,852.40	10.00	2,567.16	Replace	1	2,567.16	Replace	car
Standard	Main			COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1	4,079.80	4,079.80	10.00	3,671.82	Replace	0	0	Not Give	X11
Standard	Main			LAMP ASSY, FOG, LH	1	256.50	256.50	10.00	230.85	Replace	0	0	Not Give	X11
Standard	Main			COVER ASSY, ENGINE UNDER CENTER SET	1	511.20	511.20	30.00	357.84	Replace	1	357.84	Replace	car
Standard	Main			COVER, ENGINE UNDER SIDE RH	1	86.20	86.20	30.00	60.34	Replace	0	0	Not Give	X11
Standard	Main			COVER, ENGINE UNDER SIDE LH	1	86.20	86.20	30.00	60.34	Replace	1	60.34	Replace	car
Standard	Main			HOOD SUB-ASSY	1	1,086.30	1,086.30	30.00	746.41	Replace	0	0	Not Give	X11
Total Spare Part Cost									48,888.92	Surveyor Total 8,330.94				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									48,888.92	Final Sur Total 8,330.94				

SMRT Recommendation													Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks		
Standard	Main			SUPPORT, RADIATOR UPPER LH	1	85.20	85.20	30.00	59.64	Replace	0	0	Not Give	Xan		
Standard	Main			"MEMBER SUB-ASSY, FR LH "	1	2,342.30	2,342.30	30.00	1,839.81	Replace	0	0	Not Give	Xan		
Standard	Main			WIRE, ENGINE ROOM MAIN	1	7,323.90	7,323.90	10.00	6,591.51	Replace	0	0	Not Give	Xan		
Standard	Main			WIRE, ENGINE, NO.3	1	310.30	310.30	10.00	279.27	Replace	0	0	Not Give	Xan		
Standard	Main			WIRE, AIR CONDITIONER	1	576.30	576.30	10.00	518.67	Replace	0	0	Not Give	Xan		
Standard	Main			FENDER SUB-ASSY, FR , LH	1	1,080.70	1,080.70	30.00	742.49	Replace	1	742.49	Replace	bf		
Standard	Main			EMBLEM, SIDE PANEL (HYBRID)	1	59.10	59.10	30.00	41.37	Replace	1	41.37	Replace	neu		
Standard	Main			LINER, FR FENDER, LH	1	227.80	227.80	30.00	159.46	Replace	1	159.46	Replace	der		
Standard	Main			RETAINER, FR WHEEL RH	1	3.50	3.50	30.00	2.45	Replace	0	0	Not Give	Xan		
Standard	Main			PROTECTOR, FR FENDER LH	1	101.80	101.80	30.00	71.26	Replace	1	71.26	Replace	der		
Standard	Main			PAD, FR WHEEL LH	1	65.00	65.00	30.00	45.50	Replace	0	0	Not Give	Xan		
One Time Key In	Main			COVER SUB-ASSY, FRONT PILLAR , UPR LH	1	108.70	108.70	30.00	76.09	Replace	0	0	Not Give	Xan		
Standard	Main			WHEEL, DISC FRONT	1	2,036.30	2,036.30	30.00	1,425.41	Replace	1	1,425.41	Replace	scu		
Standard	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	1	126.74	Replace	cut		
Standard	Main			HUB & BEARING ASSY, RH & LH	1	722.10	722.10	30.00	505.47	Replace	0	0	Check	?		
Standard	Main			KNUCKLE, STEERING, LH	1	717.50	717.50	30.00	502.25	Replace	0	0	Check	?		
Standard	Main			LOWER ARM SUB-ASSY, FRONT LH	1	823.20	823.20	30.00	576.24	Replace	0	0	Check	?		
Standard	Main			ABSORBER SET, SHOCK, FRONT LH	1	511.40	511.40	30.00	357.98	Replace	0	0	Check	?		
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR LH	1	1,407.80	1,407.80	30.00	985.46	Replace	1	985.46	Replace	bf		
One Time Key In	Main			STICKER STRIDES TAXI (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	neu		
One Time Key In	Main			PILLAR, CENTER BODY, OUTER LH	1	349.50	349.50	30.00	244.65	Replace	0	0	Not Give	Xan		
One Time Key In	Main			CHECK ASSY, FRONT DOOR	1	199.40	199.40	30.00	139.58	Replace	0	0	Not Give	Xan		
One Time Key In	Main			WEATHERSTRIP, FRONT DOOR LH	1	250.70	250.70	30.00	175.49	Replace	0	0	Not Give	Xan		

Total Spare Part Cost 48,888.92

Surveyor Total 8,330.94

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 48,888.92

Final Sur Total 8,330.94

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			HINGE ASSY, FRONT DOOR , UPPER LH	1	105.50	105.50	30.00	73.85	Replace	0	0	Not Give	✓ Xan
One Time Key In	Main			HINGE ASSY, FRONT DOOR , LOWER LH	1	120.00	120.00	30.00	84.00	Replace	0	0	Not Give	✓ Xan
One Time Key In	Main			DOOR FRONT WINDOW REGULATOR SUB-ASSY, LH	1	257.80	257.80	30.00	180.46	Replace	0	0	Not Give	✓ Xan
One Time Key In	Main			DOOR FRONT MOTOR ASSY, POWER WINDOW REGULATOR , LH	1	996.60	996.60	10.00	896.94	Replace	0	0	Not Give	✓ Xan
One Time Key In	Main			WIRE, FRONT DOOR, LH	1	513.50	513.50	10.00	462.15	Replace	0	0	Not Give	✓ Xan
One Time Key In	Main			LOCK ASSY, FRONT DOOR LH	1	607.90	607.90	10.00	547.11	Replace	0	0	Not Give	✓ Xan
One Time Key In	Main			DOOR LOCK STRIKER	1	42.60	42.60	30.00	29.82	Replace	0	0	Not Give	✓ Xan
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR , LH	1	1,401.70	1,401.70	30.00	981.19	Replace	1	981.19	Replace	✓ bt
One Time Key In	Main			CHECK ASSY, REAR DOOR	1	199.40	199.40	30.00	139.58	Replace	0	0	Not Give	✓ Xan
One Time Key In	Main			HINGE ASSY, REAR DOOR , UPPER LH	1	107.00	107.00	30.00	74.90	Replace	0	0	Not Give	✓ Xan
One Time Key In	Main			HINGE ASSY, REAR DOOR , LOWER LH	1	93.90	93.90	30.00	65.73	Replace	0	0	Not Give	✓ Xan
One Time Key In	Main			DOOR REAR MOTOR ASSY, POWER WINDOW REGULATOR , LH	1	996.60	996.60	10.00	896.94	Replace	0	0	Not Give	✓ Xan
One Time Key In	Main			DOOR REAR WINDOW REGULATOR SUB-ASSY, LH	1	223.50	223.50	30.00	156.45	Replace	0	0	Not Give	✓ Xan
One Time Key In	Main			WIRE, REAR DOOR, LH	1	268.00	268.00	10.00	241.20	Replace	0	0	Not Give	✓ Xan
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR LH	1	943.10	943.10	30.00	660.17	Replace	1	0	Repair	✓ L
One Time Key In	Main			LJD ASSY, FUEL FILLER OPENING	1	164.10	164.10	30.00	114.87	Replace	0	0	Not Give	✓ Xan
Standard	Main			STICKER PETROL ONLY	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	✓ Xan
Total Spare Part Cost									48,888.92	Surveyor Total		8,330.94		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									48,888.92	Final Sur Total		8,330.94		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			2,026.00	1,000.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH PORTION	2,028.00	1,000	
Total:			2,028.00	1,000.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT HOOD	378.00	0 <i>X11</i>	
3	Main	TO RESPRAY FRONT FENDER LH	378.00	200.00	
4	Main	TO RESPRAY APRON PANEL LH	180.00	0 <i>X11</i>	
5	Main	TO RESPRAY FRONT DOOR LH	378.00	200	
6	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	100	
7	Main	TO RESRAY REAR DOOR LH	378.00	200	
8	Main	TO RESPRAY CENTRE PILLAR LH	180.00	0 <i>X11</i>	
9	Main	TO RESPRAY REAR FENDER LH	378.00	200	
10	Main	TO RESPRAY FUEL LID COVER	180.00	0 <i>XM</i>	
11	Main	TO RESPRAY RIM	180.00	0 <i>X11</i>	
Total:			3,168.00	1,100.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	0 <i>X11?</i>	request invoice
2	Main	TO WASH AND VACUUM	60.00	0 <i>X11</i>	
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	40	
4	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	60	
5	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	
6	Main	TO TRANSFER DOOR MECHANISM	240.00	100	
Total:			1,096.00	260.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
7	Main	TO REMOVE AND REFIX UNDERCARRIAGE	200.00	0 <i>X17</i>	
8	Main	TO REPLACE SUNDRY PARTS	100.00	0 <i>X17</i>	
Total:			1,096.00	260.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	48,888.92	8,330.94
Total Labour Cost	2,028.00	1,000.00
Total Spray Painting	3,168.00	1,100.00
Other	1,096.00	260.00
Overall Total	55,180.92	10,690.94
Lump Sum Repair Option		☐
Lump Sum Total	0.00	10,690.94
Surveyor Approved Amount		10,690.94
No of Repair Days*	14	8
Remarks		Part by part / Before paint photo , After repair photo FOR CHECK ITEM and REPLACE ITEM.resurvey old and new parts/ PLEASE CALL SURVEYOR RASUL / HP : 9001 0068.
Surveyor Name		Rasul
Signature		
Survey Date	18/10/2022	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	18/10/2022 12:43 (SGT)
Reported by	Driver
Date of Accident	18/10/2022 04:20 (SGT)
Exact Location of Accident	Woodlands Drive 63, Singapore
Additional Location Information	WOODLANDS DRIVE 63 TOWARDS ANG MO KIO
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5931A
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	Strides Taxi Pte Ltd
Company Reg No	1XXXXX369K
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Policy Number / Cover Note Number	D-22099115MFSH

DRIVER

Name of Driver	NG CHENG SEE
NRIC No	SXXXX075G
Date Of Birth	04/12/1956
Occupation	Outdoor

Date Of Driving Pass	06/05/1977
Driving experience	45 YEARS AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-68662672
Alt. Phone Number	-
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Address	11
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	UNKNOWN
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS TRAVELLING ALONG WOODLANDS DRIVE 63 TOWARDS ANG MO KIO WITH ONE PASSENGER (FEMALE CHINESE) ON BOARD. TRAFFIC WAS IN MY FAVOUR AND I WAS TRAVELLING STRAIGHT. SUDDENLY A VEHICLE SHC3306M (COMFORT) FAILED TO STOP AT THE TRAFFIC JUNCTION AND CONTINUED STRAIGHT. AS SUCH I APPLIED MY BRAKE TO STOP TO AVOID A COLLISION, BUT THE VEHICLE COLLIDED ONTO THE LEFT PORTION OF MY TAXI.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE TOO BIG

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Manufacturer	SHC3306M
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	-
Name of Driver	Taxi
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

IMPORTANT NOTICE

SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



Describe Circumstance of the Accident

Lined area for describing the accident circumstances.

Declaration

We declare the foregoing particulars are true in every respect

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Officer / Date
(Name as in NRIC card)



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

369K

Vehicle Details

Vehicle No.:

SHB5931A

Vehicle to be Exported:

No

Intended Deregistration Date:

18 Oct 2022

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS 5DR HATCHBACK (AUTO)

Primary Colour:

Maroon

Manufacturing Year:

2019

Engine No.:

2ZR2F15920

Chassis No.:

JTDKB3FU603088856

Maximum Power Output:

90.0 kW (120 bhp)

Open Market Value:

\$26,807.00

Original Registration Date:

12 Dec 2019

First Registration Date:

12 Dec 2019

Transfer Count:

0

Actual ARF Paid:

\$14,530.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

11 Dec 2027

PARF Rebate Amount:

\$10,897.00

Intended COE Rebate Details

COE Expiry Date:

11 Dec 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$25,581.00

COE Rebate Amount:

\$16,455.00

Total Rebate Amount:

\$27,352.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.