


Section A - Accident Details

Registration Number	SHB5931A
Case Reference Number	TAX/10/22/2060
Registration Date	12/12/2019
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	NG CHENG SEE
Type of Accident	Head To Side
Accident Date and Time	18/10/2022 4:20 AM
Accident Reported Date and Time	18/10/2022 9:07 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116620
Special Instruction to ARC, if any	TP/ LEFT PORTION PORTION/ TOWED
Prepared Date and Time	18/10/2022 10:27 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,228.00	\$1,100.00
Total Spray Cost	\$3,548.00	\$1,200.00
Total Spare Part Cost	\$56,970.36	\$15,782.73
Total Other Cost	\$1,396.00	\$410.00
TOTAL COST	\$64,142.36	\$18,492.73 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	16.0	11.0
Prepared / Adjusted By	Boon Chew Tay	Rasul (LKK) / AXA
ARC / Surveyor Sign Off Date	01/11/2022 2:27 PM	01/11/2022 12:51 PM
Signature		
Remarks	Initial 14 days / sup 2 days / total 16 days	Part by part / Before paint photo , After repair photo FOR CHECK ITEM and REPLACE ITEM.resurvey old and new parts/ PLEASE CALL SURVEYOR RASUL / HP : 9001 0068. email: rasul@lkkauto.com

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2211-0316	Invoice Number	
Quotation Date	22.11.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR CENTRE PILLAR	\$200.00	\$100.00 ✓
TO REPAIR LH PORTION	\$2,028.00	\$1,000.00 ✓
Total Labour	\$2,228.00	\$1,100.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY FRONT HOOD	\$378.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00 ✓
TO RESPRAY APRON PANEL LH	\$180.00	\$0.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00 ✓
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00 ✓
TO RESRAY REAR DOOR LH	\$378.00	\$200.00 ✓
TO RESPRAY CENTRE PILLAR LH	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00 ✓
TO RESPRAY FUEL LID COVER	\$180.00	\$0.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY CENTER PILLAR LH	\$200.00	\$100.00 ✓
TO RESPRAY FRONT PILLAR LH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$3,548.00	\$1,200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIT FRT UNDER CARRIAGE	\$300.00	\$150.00 ✓
TOWING CHARGE	\$56.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$40.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$60.00 ✓
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00 ✓
TO TRANSFER DOOR MECHANISM	\$240.00	\$100.00 ✓
TO REMOVE AND REFIX UNDERCARRIAGE	\$200.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$1,396.00	\$410.00

STRIDES Accident Vehicle Repair Estimates

 STRIDES Automotive Services Pte Ltd
 50 Woodlands Industrial Park E4, Singapore 757705
 FAX Number : 63685592
 Estimator Telephone Number : 68652623
 Accident Reporting Number : 68652672

Date Generated : 22/11/2022

User ID : PohSuan

82123-47060	WIRE, ENGINE, NO.3	0.00	\$310.30	0.00	\$0.00	Replace	Not Given	X	NN
821H2-47010	WIRE, AIR CONDITIONER	0.00	\$576.30	0.00	\$0.00	Replace	Not Given	X	NN
53802-47100	FENDER SUB-ASSY, FR, LH	1.00	\$1,060.70	30.00	\$742.49	Replace	Replace	✓	BT
75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$59.10	30.00	\$41.37	Replace	Replace	✓	NE
53876-47060	LINER, FR FENDER, LH	1.00	\$227.80	30.00	\$159.46	Replace	Replace	✓	DE
53857-12010	RETAINER, FR WHEEL RH	0.00	\$3.50	0.00	\$0.00	Replace	Not Given	X	NN
53828-47070	PROTECTOR, FR FENDER LH	1.00	\$101.80	30.00	\$71.26	Replace	Replace	✓	DE
53852-47041	PAD, FR WHEEL LH	0.00	\$65.00	0.00	\$0.00	Replace	Not Given	X	NN
60118-47020	COVER SUB-ASSY, FRONT PILLAR, UPR LH	0.00	\$108.70	0.00	\$0.00	Replace	Not Given	X	NN
42611-47450	WHEEL, DISC FRONT	1.00	\$2,036.30	30.00	\$1,425.41	Replace	Replace	✓	SCR
	TYRE	1.00	\$126.74	0.00	\$126.74	Replace	Replace	✓	CUT
43550-47020	HUB & BEARING ASSY, RH & LH	0.00	\$722.10	0.00	\$0.00	Replace	Check	X	NN
43212-47040	KNUCKLE, STEERING, LH	0.00	\$717.50	0.00	\$0.00	Replace	Check	X	NN
48069-47060	LOWER ARM SUB-ASSY, FRONT LH	0.00	\$823.20	0.00	\$0.00	Replace	Check	X	NN
48520-80639	ABSORBER SET, SHOCK, FRONT LH	0.00	\$511.40	0.00	\$0.00	Replace	Check	X	NN
67002-47163	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,407.80	30.00	\$985.46	Replace	Replace	✓	BT
	STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	✓	NEC
61312-47040	PILLAR, CENTER BODY, OUTER LH	0.00	\$349.50	0.00	\$0.00	Replace	Not Given	X	NN
68610-47040	CHECK ASSY, FRONT DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Not Given	X	NN
67862-47060	WEATHERSTRIP, FRONT DOOR LH	0.00	\$250.70	0.00	\$0.00	Replace	Not Given	X	NN
68720-12151	HINGE ASSY, FRONT DOOR, UPPER LH	0.00	\$105.50	0.00	\$0.00	Replace	Not Given	X	NN
68740-12120	HINGE ASSY, FRONT DOOR, LOWER LH	0.00	\$120.00	0.00	\$0.00	Replace	Not Given	X	NN
69802-21010	DOOR FRONT WINDOW REGULATOR SUB-ASSY, LH	0.00	\$257.80	0.00	\$0.00	Replace	Not Given	X	NN
85720-47140	DOOR FRONT MOTOR ASSY, POWER WINDOW	0.00	\$996.60	0.00	\$0.00	Replace	Not Given	X	NN
82152-47870	WIRE, FRONT DOOR, LH	0.00	\$513.50	0.00	\$0.00	Replace	Not Given	X	NN
69040-47100	LOCK ASSY, FRONT DOOR LH	0.00	\$607.90	0.00	\$0.00	Replace	Not Given	X	NN
69410-20110	DOOR LOCK STRIKER	0.00	\$42.60	0.00	\$0.00	Replace	Not Given	X	NN
67004-47211	PANEL SUB-ASSY, REAR DOOR, LH	1.00	\$1,401.70	30.00	\$981.19	Replace	Replace	✓	BT
68630-47050	CHECK ASSY, REAR DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Not Given	X	NN
68760-20122	HINGE ASSY, REAR DOOR, UPPER LH	0.00	\$107.00	0.00	\$0.00	Replace	Not Given	X	NN
68780-52031	HINGE ASSY, REAR DOOR, LOWER LH	0.00	\$93.90	0.00	\$0.00	Replace	Not Given	X	NN
85710-47150	DOOR REAR MOTOR ASSY, POWER WINDOW	0.00	\$996.60	0.00	\$0.00	Replace	Not Given	X	NN
69804-47020	DOOR REAR WINDOW REGULATOR SUB-ASSY, LH	0.00	\$223.50	0.00	\$0.00	Replace	Not Given	X	NN
82154-47380	WIRE, REAR DOOR, LH	0.00	\$268.00	0.00	\$0.00	Replace	Not Given	X	NN
61602-47180	PANEL SUB-ASSY, FENDER REAR LH	1.00	\$943.10	100.00	\$0.00	Replace	Repair	R	NN
7735047050	LID ASSY, FUEL FILLER OPENING	0.00	\$164.10	0.00	\$0.00	Replace	Not Given	X	NN
	STICKER PETROL ONLY	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X	NN
Total			\$60,768.94		\$8,785.31				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		60118-47020	COVER SUB-ASSY, FRONT PILLAR, UPR LH	1.00	\$108.70	30.00	\$76.09	Replace	Replace
		53852-47041	PAD, FR WHEEL LH	1.00	\$65.00	30.00	\$45.50	Replace	Replace

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/11/2022

User ID

PohSuan

	81056-47860	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1.00	\$4,079.80	10.00	\$3,671.82	Replace	Replace	✓ CRA
	48520-80639	ABSORBER SET, SHOCK, FRONT LH	1.00	\$511.40	30.00	\$357.98	Replace	Replace	✓ BT
	48069-47060	LOWER ARM SUB-ASSY, FRONT LH	1.00	\$823.20	30.00	\$576.24	Replace	Replace	✓ BT
	43212-47040	KNUCKLE, STEERING, LH	1.00	\$717.50	30.00	\$502.25	Replace	Replace	✓ BT
	43550-47020	HUB & BEARING ASSY, RH & LH	1.00	\$722.10	30.00	\$505.47	Replace	Replace	✓ NEC
	43330-19115	JOINT ASSY, LWR BALL, RH & LH	1.00	\$284.50	30.00	\$199.15	Replace	Replace	✓ BT
	48820-47040	LINK ASSY, FRONT STABILIZER, RH & LH	1.00	\$256.40	30.00	\$179.48	Replace	Replace	✓ BT
	45047-49195	END SET, TIE ROD, LH	1.00	\$202.30	30.00	\$141.61	Replace	Replace	✓ BT
	43420-47040	SHAFT ASSY, FRONT DRIVE, LH	0.00	\$1,355.80	0.00	\$0.00	Replace	Not Given	X SVC
	75895-47050	MOULDING, FRONT DOOR WINDOW FRAME, UPPER LH	1.00	\$47.29	30.00	\$33.10	Replace	Replace	✓ BT DE
	89543-47040	SENSOR, SPEED, FRONT LH	1.00	\$588.60	10.00	\$529.74	Replace	Replace	✓ CUT
	48609-47060	SHOCK ABSORBER MOUNTNG FRT,RH/LH	1.00	\$255.70	30.00	\$178.99	Replace	Replace	✓ BT
	53112-47310	GRILLE, RADIATOR	0.00	\$192.80	0.00	\$0.00	Replace	Not Given	X NCNN
Total				10,211.09		6,997.42			

15,782.73
+ 1100.00
+ 1610.00
18,492.73

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: