

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|---|------------------------|-----------------|-------|-----------------------|--|
| | STRIDES AUTOMO | OTIVE SERVICES PTE LTD | R | Ref: | CS/SMR22010322/Ewy3m4 | |
| | 60 WOODLANDS I E4SINGAPORE 75 | NDUSTRIAL PARK 7705 | С | Date: | 25/11/2022 | |
| | | | C | Code: | SMR | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SHB 1088K | Veh. Inspected | | SMA 3103H | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | TAX/10/22/2041 | Excess (\$) | | 0.00 | |
| | Assign From | HUA YEN | Assign Date | | 18/10/2022 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | NISSAN NOTE | c.c | | 1198 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2015 | |
| | Chassis No. | JN1TBAE12Z0982147 | Colour | | RED | |
| | Odometer | 121842 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | FAIR | | | | |
| 3. | 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 175/55 R14 | GOODYEAR | | 4 mm | |
| | L/H Front Tyre | 175/55 R14 | GOODYEAR | | 4 mm | |
| | R/H Rear Tyre | 175/55 R14 | GOODYEAR | | 4 mm | |
| | L/H Rear Tyre | 175/55 R14 | GOODYEAR | | 4 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 11/10/2022 | Inspection Date | | 18/10/2022 | |
| | Survey held at | SHU FATT AUTO WORKS | | | | |
| | BLK 1009,BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 | | | | | |
| 5a. | | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days | | | | | |
| | | | | | | |