

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SLA9198G

Make & Model: Lexus RX200T

Chassis number: JTJZAMCA502001288

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$	
		1	\$ 1,850.50	bt
1	Tailgate	1	\$ 241.20	bt
2	Tailgate windscreen glass rubber moulding	1	\$ 85.60	bt
3	Tailgate "Lexus" emblem	1	\$ 78.30	bt
4	Tailgate centre emblem	1	\$ 75.10	bt
5	Tailgate "RX200T" emblem	1	\$ 556.80	bt X nn
6	Tailgate RH lamp	1	\$ 556.80	bt X nn
7	Tailgate LH lamp	1	\$ 322.40	bt X nn
8	Tailgate lock	1	\$ 718.90	bt X nn
9	Tailgate inner trim board	1	\$ 933.20	bt X nn
10	Tailgate reverse camera	1	\$ 1,155.30	bt
11	Rear bumper	1	\$ 314.50	bt
12	Rear bumper lower garnish	1	\$ 381.00	bt X nn
13	Rear bumper RH side reverse sensor	1	\$ 381.00	bt
14	Rear bumper RH centre reverse sensor	1	\$ 381.00	bt
15	Rear bumper LH centre reverse sensor	1	\$ 381.00	bt X nn
16	Rear bumper LH side reverse sensor	1	\$ 211.90	bt X nn
17	Rear bumper RH exhaust chrome	1	\$ 211.90	bt X nn
18	Rear bumper LH exhaust chrome	1	\$ 78.60	bt X nn
19	Rear bumper RH reflector	1	\$ 78.60	bt X nn
20	Rear bumper LH reflector	1	\$ 147.80	bt
21	Rear bumper inner sponge	1	\$ 730.60	bt
22	Rear bumper reinforcement	1	\$ 83.10	bt X nn
23	Rear bumper RH side retainer	1	\$ 83.10	bt
24	Rear bumper LH side retainer	1	\$ 88.30	bt X nn
25	Rear bumper RH bracket	1	\$ 88.30	bt X nn
26	Rear bumper LH bracket	1	\$ 234.90	bt X nn
27	Rear bumper lower cover	1	\$ 910.40	bt
28	RH taillamp assy	1	\$ 90.30	bt
29	RH taillamp lower bracket	1	\$ 189.30	bt X nn
30	RH taillamp panel	1	\$ 40.00	bt X nn
31	RH taillamp lock clips	1set	\$ 910.40	bt
32	LH taillamp assy	1		bt

33	LH taillamp lower bracket	1	\$	90.30	pa
34	LH taillamp panel	1	\$	189.30	x nn
35	LH taillamp lock clips	1set	\$	40.00	x nn
36	End panel	1	\$	832.10	Bo
37	End panel inner garnish	1	\$	287.00	dp
38	Spare tyre panel top cover board	1	\$	588.00	x nn
39	Rear fender RH inner trim board	1	\$	618.90	x nn
40	Rear fender LH inner trim board	1	\$	618.90	x nn
41	Exhaust silencer	1	\$	1,865.40	x nn
42	Exhaust silencer gasket	1	\$	68.00	x nn

\$ 17,788.00 7812.40
 Parts less 10% \$ 1,778.80 -10%
 Total \$ 16,009.20 7031.16

No.	Special Nett Items	Qty	Amount S\$	
1	Tailgate windscreen glass sealant	1	\$ 80.00	lane
2	Tailgate windscreen glass inner seal	1	\$ 60.00	gout
3	Tailgate sealant	1	\$ 100.00	x nn
4	Tailgate inner trim board clips	1set	\$ 80.00	board x nn
5	Rear bumper clips	1set	\$ 80.00	gover
6	Rear bumper lower cover clips	1set	\$ 60.00	lower
7	Rear fender RH inner trim board clips	1set	\$ 80.00	x nn
8	Rear fender LH inner trim board clips	1set	\$ 80.00	x nn
9	End panel inner garnish clips	1set	\$ 50.00	lower
10	Rear number plate	1	\$ 80.00	x nn
Total:			\$ 750.00	140

No.	Labour and painting	Amount S\$	
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,400.00	600
2	Spray painting on affected areas and panels	\$ 1,200.00	700
3	Check wiring and lighting system on affected areas	\$ 100.00	30
4	Apply rust coating chemical on affected areas and panels	\$ 120.00	30
5	Remove and reinstall tailgate windscreen glass and replace sealants	\$ 280.00	60 120

1200