

(08/11/20) Wsl

ASS. REC. BY: Rahul

REF:

CC4/ASM 2201032/Rpa3

737W

CSE-2024/FEB

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBC 87975at Workshop mis Yew Tee Automobileof 39, Woodlands Close #01-12 @mtanInsured: ASM

Policy No.

Claim's No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

40K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lam Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIMIT- 33K

Veh No:

GBC 87975

Yr Regn:

2014 / FEB

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

PICK-UP

Make:

MITSUBISHI L200 TRIM DC CC 2477

Colour

WHITE

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MM C3N KB40E D0D8138

Gen. Cond:

Good / Poor / Burnt

Steering:

Good / Jammed / Leaked / Burnt or

Brake:

Good / Jammed / Leaked / Burnt or

Mod:

Nil / STD / STD A/Rim or

Tyre Size:

F:

195/5R16C

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

ROYAL BLACK

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

11/10/22

D.O.A.

18/10/22

Survey held at

Yew Tee

Des. of Damages:

FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST 5(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

ON BEHALF OF OWNER :

Policy Particulars: - THIRD PARTY CLAIM

Insured veh.	GBC8797S	Excess.
Policy No.	5119359433-01	Coverage.
Claiming Against.	SHC2009C AXA	
Insured Under.	INCOME	

Vehicle Particulars & Condition

Make & Model	Misubishi L200
Engine No.	
Chassis No.	MMCJNKB40ED008138
Odometer	
Engine CC.	
Year Of Reg.	2014
Colour.	
Parf/COE Rebate.	

Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

Description Of Damages

General Information

Accident Date. 11/10/2022
Survey held at

Yew Tee Automobile Tech Pte Ltd
39 Woodlands Close #01-12, Singapore 737856

Remarks

KINDLY LET US HAVE THE LIABILITY SOON.

Estimate Days Of Repair

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@103, 25 Kallang Road #01-61 S(417800)

Tel: 6762 3424 (3 Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

Qty.	Description Of Parts	Pricing
1	FRONT FENDER RH <i>bt</i>	\$ 840.00
1	FRONT FENDER LH <i>bt</i>	\$ 840.00
1	FRONT FENDER LAMP LH <i>X</i>	\$ 155.00
1	FRONT FENDER INNER SHIELD RH <i>form</i>	\$ 185.00
1	FRONT FENDER INNER SHIELD LH <i>form</i>	\$ 185.00
1	FRONT BUMPER <i>sea</i>	\$ 1,152.00
1	FRONT BUMPER BRACKET LH <i>?</i>	\$ 55.00
1	FRONT BUMPER EMBLEM <i>per</i>	\$ 96.00
1	BONNET <i>bt</i>	\$ 912.00
1	BONNET HINGES RH <i>X</i>	\$ 72.00
1	BONNET HINGES LH <i>X</i>	\$ 72.00
1	BONNET INSULATOR <i>?</i>	\$ 277.00
1	BONNET LOCK <i>?</i>	\$ 293.60
1	FRONT HEADLAMP RH <i>?</i>	\$ 1,296.00
1	FRONT HEADLAMP LH <i>X</i>	\$ 1,296.00
1	FRONT GRILLE RH <i>X</i>	\$ 432.00
1	FRONT GRILLE LH <i>X</i>	\$ 432.00
1	FRONT SUPPORT PANEL <i>?</i>	\$ 1,105.00
1	FRONT SUPPORT PANEL TOP GARNISH <i>?</i>	\$ 180.00
1	FRONT SUPPORT PANEL AIR INTAKE DUCT <i>?</i>	\$ 182.00
1	WIPER TANK RH <i>?</i>	\$ 175.00
1	AIR CLEANER BOX RH <i>?</i>	\$ 580.00
1	AIR CLEANER RESONATOR <i>?</i>	\$ 440.00
1	AIR CLEANER RESONATOR JOINT PIPE <i>?</i>	\$ 455.00
1	FRONT DOOR RH <i>bt</i>	\$ 1,480.00
1	FRONT DOOR LH <i>bt</i>	\$ 1,480.00
1	FRONT DOOR PILLAR RH <i>bt</i>	\$ 680.00
1	FRONT DOOR PILLAR LH	\$ 680.00
1	FRONT DOOR TOP HINGES RH <i>?</i>	\$ 105.00
1	FRONT DOOR BOTTOM HINGES RH <i>?</i>	\$ 105.00
1	FRONT DOOR TOP HINGES LH <i>X</i>	\$ 105.00
1	FRONT DOOR BOTTOM HINGES LH <i>X</i>	\$ 105.00
1	FRONT DOOR LOCK RH <i>?</i>	\$ 430.00
1	FRONT DOOR LOCK LH <i>X</i>	\$ 430.00
1	FRONT DOOR LOCK CATCH RH <i>X</i>	\$ 55.00
1	FRONT DOOR LOCK CATCH LH <i>X</i>	\$ 55.00
1	FRONT DOOR INNER BOARD RH <i>?</i>	\$ 385.00
1	FRONT DOOR GLASS RH <i>bt</i>	\$ 480.00
1	FRONT DOOR GLASS LH <i>bt</i>	\$ 480.00
1	FRONT DOOR GLASS REGULATOR RH <i>?</i>	\$ 377.00
1	FRONT DOOR GLASS REGULATOR MOTOR RH <i>?</i>	\$ 285.00

YEW TEE AUTOMOBILE TECH PTE LTD

3

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: ytauto@singnet.com.sg

Branch: Synergy@KB, 2F, 3rd Bldg Road 4 #01-61 S(417800)

Tel: 6702 4133 (3Lines) Fax: 6702 3773

EMAIL: ytauto@singnet.com.sg

ROC: 2010110001, CST: 200311009C

Website: www.ytauto.com.sg

Qty.	Description Of Parts	Pricing
1	FRONT DOOR GLASS OUTER MOULDING RH <i>at</i>	\$ 255.00
1	FRONT DOOR GLASS OUTER MOULDING LH <i>at</i>	\$ 255.00
1	FRONT DOOR GLASS CHANNEL RH ?	\$ 185.00
1	FRONT DOOR GLASS CHANNEL LH <i>X</i>	\$ 185.00
1	FRONT SIDE MIRROR RH <i>X</i>	\$ 660.00
1	FRONT SIDE MIRROR LH <i>mis</i>	\$ 660.00
1	FRONT SIDE MIRROR OUTER COVER RH <i>ca</i>	\$ 185.00
1	FRONT SIDE MIRROR OUTER COVER LH <i>mis</i>	\$ 185.00
1	FRONT SIDE MIRROR GLASS LH <i>mis</i>	\$ 180.00
1	FRONT DOOR RUBBER RH <i>ne</i>	\$ 255.00
1	FRONT DOOR RUBBER LH <i>ne</i>	\$ 255.00
1	FRONT DOOR OUTER HANDLE LH <i>sc</i>	\$ 265.00
1	FRONT DOOR OUTER HANDLE REAR KNOB LH <i>X</i>	\$ 135.00
1	FRONT DOOR STEP PANEL RH <i>de</i>	\$ 380.00
1	FRONT DOOR STEP PANEL TOP GARNISH RH <i>sc</i>	\$ 185.00
1	FRONT DOOR FLOOR PANEL RH <i>repair</i>	\$ 1,410.00
1	REAR DOOR RH <i>bt</i>	\$ 1,450.00
1	REAR DOOR LH <i>bt</i>	\$ 1,450.00
1	REAR DOOR TOP HINGES RH <i>X?</i>	\$ 105.00
1	REAR DOOR BOTTOM HINGES RH <i>X?</i>	\$ 105.00
1	REAR DOOR TOP HINGES LH <i>X</i>	\$ 105.00
1	REAR DOOR BOTTOM HINGES LH <i>X</i>	\$ 105.00
1	REAR DOOR LOCK RH ?	\$ 410.00
1	REAR DOOR LOCK LH <i>X</i>	\$ 410.00
1	REAR DOOR LOCK CATCH RH <i>X</i>	\$ 55.00
1	REAR DOOR LOCK CATCH LH <i>X</i>	\$ 55.00
1	REAR DOOR INNER BOARD RH ?	\$ 395.00
1	REAR DOOR GLASS REGULATOR RH ?	\$ 377.00
1	REAR DOOR GLASS REGULATOR MOTOR RH ?	\$ 285.00
1	REAR DOOR GLASS OUTER MOULDING RH <i>de</i>	\$ 255.00
1	REAR DOOR GLASS OUTER MOULDING LH <i>de</i>	\$ 255.00
1	REAR DOOR RUBBER RH <i>ne</i>	\$ 230.00
1	REAR DOOR RUBBER LH <i>ne</i>	\$ 230.00
1	REAR DOOR OUTER HANDLE LH <i>sc</i>	\$ 265.00
1	REAR DOOR OUTER HANDLE REAR KNOB LH <i>X</i>	\$ 135.00
1	REAR DOOR FLOOR PANEL RH <i>repair</i>	\$ 1,410.00
1	FRONT WINDSCREEN GLASS <i>bro</i>	\$ 850.00
1	FRONT WINDSCREEN GLASS MOULDING <i>ne</i>	\$ 80.00
1	FRONT WINDSCREEN PILLAR RH <i>bt</i>	\$ 590.00
1	FRONT WINDSCREEN PILLAR LH <i>bt</i>	\$ 590.00
1	FRONT WINDSCREEN PILLAR INNER GARNISH RH ?	\$ 195.00

YEW TEE AUTOMOBILE TECH PTE LTD

4

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@K3, 25 Padi Road Road 4 #01-61 S(417800)

Tel: 6702 2113 (2Lines) Fax: 6700 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.yewtee.com.sg

Qty.	Description Of Parts	Pricing
1	FRONT WINDSCREEN PILLAR INNER GARNISH LH ?	\$ 195.00
1	FRONT WIPER ARM RH bt/	\$ 130.00
1	FRONT WIPER ARM LH bt/	\$ 130.00
1	CENTRE PILLAR RH bt/	\$ 660.00
1	CENTRE PILLAR LH repn/	\$ 660.00
1	CENTRE PILLAR INNER PANEL RH ?	\$ 477.00
1	CENTRE PILLAR INNER PANEL LH X	\$ 477.00
1	CENTRE PILLAR INNER GARNISH RH ?	\$ 256.00
1	ROCKER PANEL RH bt/	\$ 1,280.00
1	REAR TAILLAMP RH X	\$ 366.00
1	REAR TAILLAMP LH ca/	\$ 366.00
1	REAR AXLE X	\$ 1,595.00
1	FRONT LOWER ARM LH X	\$ 420.00
1	FRONT UPPER ARM LH X	\$ 440.00
1	FRONT KNUCKLE ARM LH X	\$ 480.00
1	FRONT SHOCK ABSORBER LH X	\$ 450.00
1	REAR CARRIAGE SIDE PANEL RH repn/	\$ 1,695.00
1	REAR CARRIAGE SIDE PANEL LH bt/	\$ 1,695.00
1	REAR CARRIAGE SIDE PANEL LOWER REFLECTOR RH X	\$ 155.00
1	REAR CARRIAGE SIDE PANEL LOWER REFLECTOR LH ca/	\$ 155.00
1	REAR CARRIAGE SIDE PANEL FRONT PROTECTOR RH de/	\$ 235.00
1	REAR CARRIAGE SIDE PANEL FRONT PROTECTOR LH X	\$ 235.00
1	ROOF TOP PANEL bu/	\$ 1,350.00
1	ROOF TOP PANEL INNER LINING de/	\$ 780.00
1	ROOF TOP SIDE MOULDING RH ca/	\$ 490.00
1	ROOF TOP SIDE MOULDING LH ca/	\$ 490.00
1	ROOF TOP ANTENNA ?	\$ 135.00
1	ROOF TOP ANTENNA BASE ?	\$ 85.00
1	ROOF TOP INNER CENTRE LAMP ?	\$ 185.00
1	REAR VIEW MIRROR ?	\$ 140.00
1	REAR VIEW MIRROR BASE ?	\$ 110.00
1	REAR VIEW MIRROR JOINT ?	\$ 75.00
1	FRONT TOP DASHBOARD ?	\$ 2,850.00
1	ENGINE FRONT MOUNTING X	\$ 250.00
1	ENGINE RH MOUNTING X	\$ 240.00
1	ENGINE LH MOUNTING X	\$ 270.00
1	ENGINE REAR MOUNTING X	\$ 230.00
1	CHASSIS FRAME RH X	\$ 3,880.00
Subtotal		\$ 59,563.60
Less 10%		\$ 5,956.36
		\$ 53,607.24

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3273 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Syntex@Pte., 23 Kall Bahir Road 4 #01-61 S(417800)

Tel: 6702 2145 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200313009C GST: 200311009C

Website: www.utauto.com.sg

Qty.	Description Of Parts	Pricing
1	FRONT BUMPER CLIPS (1 SET) <i>ne</i>	\$ 45.00 <i>30</i>
1	BONNET INSULATOR CLIPS (1 SET) <i>ne</i>	\$ 30.00
1	ERP BRACKET <i>ne</i>	\$ 18.00 <i>10</i>
1	FRONT WINDSCREEN SEALANT <i>ne</i>	\$ 100.00 <i>60</i>
1	FRONT WIPER BLADE RH <i>cut</i>	\$ 15.00 <i>10</i>
1	FRONT WIPER BLADE LH <i>cut</i>	\$ 15.00 <i>10</i>
1	REAR WHEEL RIM LH <i>cut</i>	\$ 300.00
1	FRONT WHEEL RIM LH <i>cut</i>	\$ 300.00
1	REAR CARRIAGE TOP COVER (ALUMINIUM) <i>cut</i>	\$ 1,850.00 <i>? price</i>
1	ROOF TOP SIDE MOULDING RH CLIPS (1 SET)	\$ 80.00 <i>40</i>
1	ROOF TOP SIDE MOULDING LH CLIPS (1 SET)	\$ 80.00 <i>40</i>
	S/N	\$ 2,835.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LABOUR

To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts.	\$ 100.00 <i>40</i>
To dismantle and reft rear carriage top aluminium cover.	\$ 1,000.00 <i>200</i>
To remove and refit front dashboard & related wire harness & related parts.	\$ 380.00 <i>150 200</i>
To do up interior cleaning and chemical wash.	\$ 250.00 <i>X</i>
To remove and refit rear cushion fittings.	\$ 100.00 <i>60</i>
To transfer 4 doors.	\$ 320.00 <i>200</i>
To dismantle and refit front undercarriage.	\$ 220.00 <i>X</i>
To dismantle and refit rear undercarriage.	\$ 220.00 <i>X</i>
To dismantle and refit front windscreen glass.	\$ 100.00
To conduct computer wheel alignment.	\$ 80.00 <i>60</i>
To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.	\$ 6,000.00 <i>3000</i>
To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.	\$ 3,000.00 <i>250</i>

LABOUR \$ 11,770.00

Sub Total. \$ 68,212.24

7% GST \$ 4,774.86

Grand Total \$ 72,987.10

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	14/10/2022 10:06 (SGT)
Reported by	Driver
Date of Accident	11/10/2022 09:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	TRAFFIC LIGHT T-JUNCTION AT BUKIT BATOK CRESCENT AND BUKIT BATOK ST 23
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC8797S
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	SHECEY (SINGAPORE) PTE LTD
Company Reg No	1XXXXX737W
Email Address	SALES@SHECEY.COM.SG
Mobile Phone No	(Phone) +65-62763383
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	L200
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	0

INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5119350433-01

DRIVER

Name of Driver	HAMZA BIN RAHIM
NRIC No	SXXXX711J
Date Of Birth	28/12/1994

Occupation	Outdoor
Date Of Driving Pass	05/04/2017
Driving experience	5 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97278812
Alt. Phone Number	-
Email Address	HADDEN.HAMZA@OUTLOOK.SG
Address	BLK 22 TEBAN GARDENS ROAD #25-129
Address complement	-
Postcode	600022
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Cross Junction
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER FOR ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC2009C
Vehicle Manufacturer	-
Vehicle Model	-

Vehicle Variant	-
Vehicle Colour	Blue
Vehicle Category	Taxi
Name of Driver	RAHMAT
Contact Number	(Phone) +65-83858343
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	HAMZA BIN RAHIM
Gender	Male
Phone No	(Phone) +65-97278812
Address	BLK 22 TEBAN GARDENS ROAD #25-129
Address Complement	-
Post Code	600022
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	GBC8797S
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes

INJURED 2

Name of injured person	RAHMAT
Gender	Male
Phone No	(Phone) +65-83858343
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SHC2009C
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

HECEY (SINGAPORE) PTE LTD
53 BUKIT KATOK CRESCENT
#07-30/31 UNITY CENTRE
SINGAPORE 658077
TEL: 6276 3383 FAX: 6316 2324
E-Mail: sales@hecey.com.sg

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A 980077-5

B 5HE2007C

Describe Circumstances of the Accident

Refer to police report No: T/2022/011/305B

Declaration

I/We declare the foregoing particulars are true in every respect.

WILLIS TOWERS WATSON LTD
11 BRISTOL SQUARE
ROYAL LANCY CENTRE
NEWCASTLE 166071
TEL: 01276 336131 FAX: 01276 336132
Signature/Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Officer
Witnessed



SINGAPORE POLICE FORCE



T/20221011/7058

Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

1 of 3

Report No. T/20221011/7058

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/10/2022 21:26		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: HAMZA BIN RAHIM			Address: 22 TEBAN GARDENS ROAD #25-129 SINGAPORE 600022		
ID Type / ID No.: NRIC NO / S9448711J			Contact No.: Home/Office: Mobile: 97278812		
Nationality: SINGAPORE CITIZEN			Email: HADDEN.HAMZA@OUTLOOK.SG		
Sex: Male	Age: 27	Date of Birth: 28/12/1994	Type of Informant: Driver		
Race: Boyanese			Language: English		Institution / School Name:
Occupation: Field Technician			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 11/10/2022 09:30	Type of Location: T-Junction
Location: BUKIT BATOK STREET 23				
Weather: Sunny		Road Surface: Dry	Road Speed Limit: 20 Km/h	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Conditio	No of
GBC8797S	Lorry					0
	Car	HYUNDAI	Ioniq	Blue	Seriously Damaged	0



CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	HAMZA BIN RAHIM	ID No.	S9448711J
Related Vehicle	GBC8797S (Lorry)	Contact No.	97278812
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL
Driver			
Name	RAHMAT	ID No.	NIL
Related Vehicle	(Car)	Contact No.	83858343
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	11/10/2022	Date	11/10/2022
No. of Days granted Medical Leave	NIL	Degree of	Slight

Brief Details.

At about 9.30am, I was driving a pickup truck, Mitsubishi L200, from Bukit Batok Crescent heading towards Bukit Batok St 23 towards PIE. When the traffic light turned green, i drove off after the first vehicle move and that was when the taxi from my right side collided with my vehicle from head to side, causing my vehicle to overturn and i've suffered giddiness, headbump, stiffed neck, scratches and minor injuries.



**SINGAPORE
POLICE FORCE**



T/20221011/7058

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20221011/7058

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
THABAGESH JEYATHESH
Contact No.: 65476178

Signature Of Informant:

The identity of the person making this report has been authenticated by Singpass. No signature is required.

Date/Time:
11/10/2022 21:26

Classification Of Case:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	737W

Vehicle Details

Vehicle No.:	GBC87975
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Oct 2022
Vehicle Make:	MITSUBISHI
Vehicle Model:	L200 TRITON DOUBLE CAB (M/T)
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	4D56UCZZ3344
Chassis No.:	MMCJNKB40ED008138
Maximum Power Output:	-
Open Market Value:	\$18,900.00
Original Registration Date:	11 Feb 2014
First Registration Date:	11 Feb 2014
Transfer Count:	1
Actual ARF Paid:	\$18,900.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	10 Feb 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$51,002.00
COE Rebate Amount:	\$6,700.00
Total Rebate Amount:	\$6,700.00

The information contained herein is correct as at 18 Oct 2022

OK

Mitsubishi Triton L200 Double-Cab 2.5M

Overview Financial Accessories Similar Research Photos Map

Price	\$37,500	Lifespan ?	12-Jan-2034
Depreciation ?	\$30,350 /yr View models with similar depre	Reg Date	13-Jan-2014 (1yr 2mths 25days COE left)
Mileage	184,300 km (21k /yr)	Manufactured ?	2013
Road Tax ?	N.A.	Transmission	Manual
Dereg Value ?	\$6,858 as of today (change)	Fuel Type	Diesel
COE ?	\$55,503	OMV ?	\$18,315
Engine Cap	2,477 cc	ARF ?	\$18,315
Curb Weight	1,880 kg	No. of Owners ?	2
Type of Vehicle	Truck		