

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3074B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR RH	BENT	2,707.70	2,707.70
1	FRONT DOOR UPPER HINGE RH	NOT NECESSARY	113.60	-
1	FRONT DOOR LOWER HINGE RH	BENT	113.60	113.60
1	FRONT FENDER RH	BENT	588.80	588.80
	LESS 20% DISCOUNT		-704.74	-682.02
			2,818.96	2,728.08
<u>NETT ITEMS</u>				
1	FRONT DOOR COMFORTDELGRO RH (N)	NECESSARY	75.00	75.00
	LESS 10% DISCOUNT		-7.50	-7.50
			67.50	67.50
<u>SPECIAL NETT ITEMS</u>				
1	FRONT DOOR ADV.STICKER RH (SN)	CUT	100.00	100.00
1	FRONT FENDER ADV.STICKER RH (SN)	CUT	100.00	100.00
			200.00	200.00
<u>LABOUR</u>				
	PANEL BEATING.		800.00	525.00
	SPRAY PAINTING CHARGE.		600.00	600.00
	TUFF KOTE.		100.00	30.00
	TOWING FEE (NPA).		-	-
			1,500.00	1,155.00
GRAND TOTAL			4,586.46	4,150.58

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,300.00
---	--	--	-----------------

Report Ref No. NS/INC22010329/Tcm4



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.