



1

of 2 ?



100%

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Ref: CS/CTI22010330/Tny3

Date: 18/10/2022

Code: CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLM 9176G	Veh. Inspected	SBS 3901G
Policy No.	DMPCSNW00098102201	Coverage (\$)	0.00
Claim No.	SNM22D207444/C02	Excess (\$)	0.00
Assign From	LYNN KHONG	Assign Date	18/10/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	12/10/2022	Inspection Date	19/10/2022
Survey held at	SBS TRANSIT LTD (Branch) BEDOK NORTH DEPOT 1470 BEDOK NORTH AVE 4 SINGAPORE 489946		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
