

Simon. Z. X.  
Office Tel. 6244 4515 P(96)



Accident Reference & Bus No: **AR-2022-2969 - SBS3901G with SLM9176G**

Activated date: **Tuesday, 18 October 2022 11:46**

Activated by: Ang Chong Boon <angcb@sbstransit.com.sg>

Name of Surveyor: Guo Qiang <guoqiang@lkkauto.com>

Company Name: LKK Auto

Date Surveyed: 19<sup>th</sup> Oct 2022, 13:40 hrs

Require

Resurvey 1 Date:

Resurvey 2 Date:

Final Endorsement by Surveyor: *Guo Qiang*

✗ Replace: LHR 2 X body panels;  
✓ *CRS*

✗ Repair & respray paint. LHR<sup>S</sup> body  
from LHF deflector  
to LHR Lamp Cover.

Estimate (before GST) for

*8288 0282 before part photos.  
19/10  
1:51*

- ☐ Parts cost: **\$ TBA**
- ☐ Contractor Labour cost: **\$ TBA**
- ☐ Workshop Labour cost: **\$ 188.00**
- ☐ Advertisement Cost: **\$ TBA**
- ☐ Repair period: **3 days** ✓

- ☐ Tow Cost: **\$ 0**
- ☐ Loss of use: **Not required by surveyor**
- ☐ Overheads: **Not required by surveyor**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts price agreed on the estimation
- Third party claims on "without Prejudice" basis
- No illegal modification allowed
- Supplemental survey on the surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: