

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010334/TQY3E2**Date:** 14/02/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNA00018502200

**Claimant Vehicle
No :** SNA1866R**Insured Vehicle
No :** SND3594X

Date of Loss: 15/10/2022

Nature of Claim: TP

Claim
No: SNM22D207402/C02/KHONGLHDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNA1866R**

Make & Model: BMW 216I, 1.5 (A)

Engine No: 38896345B38A15A

Reg. Date: 10/06/2021 (Man. Year: 2021)

Chassis No: WBA6V120705T42771

Colour: Black

Odometer: 32177 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R17

Rear Tyre Size: 205/55 R17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,382.50	9,674.55	6,707.95	40.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,720.00	1,750.00	970.00	35.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,102.50	11,424.55	7,677.95	40.19
Approved Total (Overridden) (S\$)		8,000.00		
(S\$)	19,102.50	8,000.00	11,102.50	58.12
+ GST 7.00/7.00% (S\$)	1,337.18	560.00	777.18	58.12
Nett Amount (S\$)	20,439.68	8,560.00	11,879.68	58.12

INSPECTION

Date of Assignment: 18/10/2022

Date Inspected: 18/10/2022 Inspected At:

Juzz Performance Pte Ltd (HQ)
8 Kaki Bukit Avenue 4 #03-51/52 PREMIER @Kaki
Bukit
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Feb 2023)
Parts:	M1-MPV	BMW 216I 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA1866R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH FRONT RIM	Cut	997.35 F	*997.35 FL
2	1		*DRIVER DOOR	Bent	1,159.75 F	*1,159.75 FL
3	1		*RH FRONT DOOR LOCK	Not Necessary	468.00 F	*- FL
4	1		*RH FRONT DOOR INNER COWLING	Not Necessary	238.00 F	*- FL
5	1		*RH FRONT FENDER	Repair	2,420.00 F	*- FL
6	2		*RH FRONT FENDER INNER COWLING	Not Necessary	446.00 F	*- FL
7	1		*RH FRONT FENDER INNER TRIM	Not Necessary	600.00 F	*- FL
8	1		*RH SIDE SKIRTING	Deformed	398.00 F	*398.00 FL
9	1		*BMW DOOR SEAL	Necessary	300.00 F	*300.00 FL
10	1		*BMW STEERING RACK	Bent	5,594.40 F	*5,594.40 FL
11	1		*RH FRONT ARM BUSHING	Not Necessary	220.00 F	*- FL
12	1		*RH FRONT LOWER ARMS	Not Necessary	320.00 F	*- FL
13	1		*RH FRONT VERTICAL LINK	Not Necessary	105.00 F	*- FL
14	1		*DRIVE SHAFT	Bent	2,300.00 F	*2,300.00 FL
15	1		*RHF SHOCK ABSORBER	Not Necessary	720.00 F	*- FL
16	20		*FENDER INNER COWLING CLIPS	Not Necessary	96.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	16,382.50	10,749.50
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	1,074.95
Total Parts (\$\$)	16,382.50	9,674.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & INSTALL ABOVE PARTS	New	600.00	300.00
2	LABOUR TO SPRAY PAINT AFFECTED PARTS / AREAS	New	900.00	700.00
3	LABOUR TO PANEL BEAT AFFECTED AREAS	New	500.00	300.00
4	LABOUR TO TRANSFER DOOR MECHANISM	New	100.00	60.00
5	LABOUR TO CONDUCT WATER LEAKAGE TEST	New	80.00	30.00
6	TO PERFORM CODING & RESET OF ELECTRONIC AND ELECTRICAL DEVICES	New	380.00	200.00
7	WHEEL ALIGNMENT	New	160.00	160.00
Gross Labour Cost (\$)			2,720.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >