

HD Perfect Autowork Pte Lt

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:jlperfectautowok@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 17.10.2022

TO : ERGO MOTOR CLAIMS DEPTS
VEHICLE NO : SMM6588J
MODEL : TOYOTA HARRIER
DATE OF ACCIDENT : 17.10.2022
TIME OF ACCIDENT : 11:45HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR DOOR RH	1	\$ 1,550.60	\$ 1,550.60
2	REAR DOOR INNER TRIM RH	1	\$ 1,016.80	\$ 1,016.80
3	REAR DOOR SPEAKER RH	1	\$ 225.30	\$ 225.30
4	REAR DOOR GLASS CHANNEL RH	1	\$ 183.70	\$ 183.70
5	REAR DOOR OUTER HANDLE RH	1	\$ 364.70	\$ 364.70
6	REAR DOOR OUTER STRIP MOULDING RH	1	\$ 158.70	\$ 158.70
7	REAR DOOR INNER LOCK RH	1	\$ 600.20	\$ 600.20
8	REAR DOOR INNER LOCK CATCHER RH	1	\$ 98.60	\$ 98.60
9	REAR DOOR WEATHER STRIP RH	1	\$ 275.60	\$ 275.60
10	REAR FENDER RH	1	\$ 1,531.80	\$ 1,531.80
11	REAR FENDER INNER PANEL RH	1	\$ 867.10	\$ 867.10
12	REAR FENDER QUARTER GLASS RH	1	\$ 282.60	\$ 282.60
13	REAR FENDER INNER COWLING RH	1	\$ 247.30	\$ 247.30
14	REAR ABS SENSOR RH	1	\$ 417.60	\$ 417.60
15	REAR SHOCK ABSORBER RH	1	\$ 152.10	\$ 152.10
16	REAR WHEEL HUP WITH BEARING RH	1	\$ 1,008.20	\$ 1,008.20
17	REAR ANTI ROLL BAR LINKAGE RH	1	\$ 179.30	\$ 179.30
18	REAR LOWER ARM RH	1	\$ 524.60	\$ 524.60
19	REAR KNUCKLE ARM RH	1	\$ 465.20	\$ 465.20
20	REAR ADJUSTABLE ARM RH	1	\$ 291.60	\$ 291.60
21	REAR CONTROL ARM RH	1	\$ 271.20	\$ 271.20
22	REAR WHEEL RIM RH	1	\$ 2,604.90	\$ 2,604.90
23	TAIL LAMP RH	1	\$ 689.60	\$ 689.60
24	REAR BUMPER	1	\$ 904.80	\$ 904.80
25	REAR BUMPER INNER SIDE GRANISH RH	1	\$ 204.90	\$ 204.90

6743-70

TO : ERGO MOTOR CLAIMS DEPTS
 VEHICLE NO : SMM6588J
 MODEL : TOYOTA HARRIER
 DATE OF ACCIDENT : 17.10.2022
 TIME OF ACCIDENT : 11:45HRS

26	REAR BUMPER LOWER	1	\$ 466.10	\$ 466.10	mis
27	REAR BUMPER REFLECTOR	2	\$ 85.60	\$ 171.20	X nn
28	REAR BUMPER SIDE RETAINER	2	\$ 82.70	\$ 165.40	Rflang
29	REAR BUMPER SPONGE	1	\$ 89.30	\$ 89.30	X nn
30	REAR BUMPER REVERSE SENSOR	2	\$ 397.80	\$ 1,591.20	am 758-60
31	REAR BUMPER REVERSE SENSOR HOLDER	4	\$ 28.90	\$ 115.60	rec
32	REAR BUMPER REVERSE SENSOR WIREHARNES	1	\$ 288.10	\$ 288.10	X nn 1460

7431.10

5573.32

TOTAL PRICE \$ 18,003.90
 LESS 25% \$ 4,500.98
 SUB TOTAL PRICE \$ 13,502.93

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR DOOR SEALANT RH	1	\$ 150.00	\$ 150.00	40ner
2	REAR DOOR INNER TRIM CLIP RH (SET)	1	\$ 80.00	\$ 80.00	20ner
3	REAR DOOR WINDOW SIDE GARNISH CLIP (SET)	1	\$ 60.00	\$ 60.00	X }
4	REAR SEAT SIDE GARNISH CLIP RH (SET)	1	\$ 80.00	\$ 80.00	X }
5	SIDE SKIRT CLIP (SET)	1	\$ 80.00	\$ 80.00	X }
6	REAR FENDER SEALANT RH	1	\$ 150.00	\$ 150.00	60ner
7	REAR FENDER INNER COWLING CLIP (SET)	1	\$ 60.00	\$ 60.00	20ner
8	REAR FENDER INNER TRIM CLIP (SET)	1	\$ 80.00	\$ 80.00	X d7
9	REAR FENDER GLASS SEALANT RH	1	\$ 80.00	\$ 80.00	40ner
10	REAR FENDER GLASS INNER SHIELD RH	1	\$ 60.00	\$ 60.00	X }
11	REAR FENDER GLASS SOLAR FILM RH	1	\$ 150.00	\$ 150.00	X }
12	TAIL LAMP CLIP (SET)	1	\$ 60.00	\$ 60.00	X }
13	REAR BUMPER CLIP (SET)	1	\$ 120.00	\$ 120.00	30ner
14	REAR WHEEL TYRE RH	1	\$ 650.00	\$ 650.00	X }
15	WHEEL CAP (SET)	1	\$ 120.00	\$ 120.00	X }
16	BRAKE OIL	1	\$ 30.00	\$ 30.00	X }

TOTAL \$ 2,010.00

210

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 2,000.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	900
3	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	80

TO : ERGO MOTOR CLAIMS DEPTS
 VEHICLE NO : SMM6588J
 MODEL : TOYOTA HARRIER
 DATE OF ACCIDENT : 17.10.2022
 TIME OF ACCIDENT : 11:45HRS

4	TUFF COAT	\$ 250.00	50.
5	WIRING CHECK	\$ 250.00	40
6	REMOVE AND REFIX REAR FENDER GLASS LH	\$ 100.00	50 X un
7	REMOVE AND REFIX SAFETY BELT	\$ 250.00	X un
8	FOUR WHEEL ALIGNMNET	\$ 120.00	80
9	REMOVE & REFIX AUDIO SPEAKER	\$ 120.00	X un
10	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	40
11	TRANFER REAR DOOR MECHANISM LH	\$ 80.00	60
12	REMOVE & REINSTALL REAR WINDOW GLASS RH	\$ 60.00	40
13	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	7,150
14	RESET ABS LIGHT	\$ 350.00	X un
15	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 350.00	150✓

TOTAL \$ 6,610.00

2390

ESTIMATE REPORT

TOTAL PARTS COST : \$ 15,512.93
 TOTAL LABOUR COST : \$ 6,610.00
 TOTAL REPAIR COST : \$ 22,122.93

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES

YOUR PATRONS hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To also survey damaged parts during resurvey
 • Parts prices are subject to confirmation
 • No legal modification(s) is allowed
 • Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjim 97495749 / 62563561
 WP 18/10/22 @ 3pm
 4/5 hours after repair
 07 days
 tanjim@khauto.com
 Total: 8173.32
 4/5 : 6.5K ✓