



南方摩哆

Southern Motor

Business Reg. No: 234147/00L

Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762

Tel: 6273-0369 (3 Lines) Fax: 6274-6614

18-Oct-22

China Taiping Insurance Singapore Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore (079909)

Dear Sirs,

RE: Cost of repair to Yamaha Nmax155 ABS CVT - FBU1629X

1pc of Front Foot Plate Set	S\$	240.00
1pc of Brake Lever LH		22.00
1pc of Brake Lever RH		22.00
1pc of Handle Bar		75.00
1pc of Exhaust Pipe Cover		60.00
1pc of Rear Givi Box		140.00
		<hr/>
		559.00
	Less 10%	55.90
		<hr/>
	Nett	503.10
	LTA Fees	7.45
	Labour	150.00
		<hr/>
		<u>\$660.55</u>

Yours Faithfully,

Southern Motor



Date: 18 Oct 2022

Southern Motor
Blk 1006 Bukit Merah Lane 2
#01-10
Singapore 159762

Motor Claims Department
China Taiping Insurance Singapore Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909

Dear Sirs,

RE: ACCIDENT INVOLING FBU1629X AND SJE3381K ALONG
302 Tiong Bahru Road ON 15-10-2022 AT 13:11PM

Please be informed that the above-said motorcycle bearing registration no: FBU1629X was seriously damaged during the above-said accident and was beyond economic repair.

Kindly arrange for your surveyor to survey the above-mentioned motorcycle at Blk 1006, Bukit Merah Lane 2 #01-10 Singapore 159762. (Tel:62730369)

Thanking you in advance,

Yours Faithfully,



Enc.