



南方摩哆

Southern Motor

Business Reg. No: 234147/00L

Block 1006, Bukit Merah Lane 2, #01-10, Singapore 159762

Tel: 6273-0369 (3 Lines) Fax: 6274-6614

18-Oct-22

China Taiping Insurance Singapore Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore (079909)

Dear Sirs,

RE: Cost of repair to Yamaha Nmax155 ABS CVT - FBU1629X

1pc of Front Foot Plate Set	/ CVT	S\$	240.00	✓
1pc of Brake Lever LH	/ CVT		22.00	✓
1pc of Brake Lever RH	/ CVT		22.00	✓
1pc of Handle Bar	/ BI		75.00	✓
1pc of Exhaust Pipe Cover	/ CVT		60.00	✓
1pc of Rear Givi Box	/ CVT		140.00	✓
			559.00	
		Less 10%	55.90	
		Nett	503.10	
		LTA Fees	7.45	×
		Labour	150.00	100✓
			<u>\$660.55</u>	

Steve (LKK) 8377 8813

19/10/22, 10.00

W NL

P/P

M BL Y

3 dgs

P/P - \$603.10

Yours Faithfully,
Southern Motor



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: