

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLW 1076L
 at Workshop m/s RP.
 of _____
 Insured: SMB 59575
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SLW 1076L Yr Regn: 30/01/18
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: KIA cerato K3 c.c 1591
 Colour: Brown A/C: Insured / Std / NI / NA
 Sp. Reading: 270955 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KNAFX41MJS761066
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or affected
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/55R16
 R: Farrad

(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or DUMHO
 Front 6 mm Rear 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 L/Bal. 6 mm
 D.O.A. 12/10/22 D.O.I. 19/10/22
 Survey held at _____

Bal. or Market Value: \$60k.
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 9 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS 061h
 Date: _____ Person Contacted: LTA 31154
 Vehicle: IN / OUT

Des. of Damages : Frt / Rear / O/S / N/S / UIC / Rooftop or
0/5 Frt, 0/5 Body &
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Dep 11k.</u>
	<u>headly 2210 Fr door 1542 Rear door 1361</u>
	<u>have 6.4</u>
<u>8/11/22</u>	<u>1/5 @ 13,000 informed Aln. (Med # 16387.10, 56%)</u>

Date/Time, File Pass to? : Preli. Report : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) _____

Days Of Repair: 9
 Resurvey No. of Trip: 2

Report Format : TP
 Lump Sum / I.B.f: (\$) 13000

Add Fee: : Site Insp (\$)) : S + RS) SI
 : Interview (\$)) : Photos
 : Tech. Invs (\$)) : Others
 : Weekend (\$))

TOTAL

FASTECH AUTO PTE LTD
 1 Kaki Bukit Ave 6 #01-48 Autobay
 Singapore 417883
 Tel No: 67452063/ 67467158 Fax No: 67458520
 Tax Reg No : 20006262D

Not Authorized
 19/10/22
 2/s \$13,000/
 9 days.

VEHICLE No: SLW 1076L

NETT ITEM 316.50 s/n

QTY	DESCRIPTION	REMARKS	PRICE	NETT ITEM
1PC	FRONT BUMPER	Re/Torn	637.502 s/n	\$788.00 / 502 s/n
1PC	FRONT BUMPER SIDE RETAINER O/S	one		\$32.00
1PC	FRONT BUMPER FOG LAMP O/S	17		\$305.00 X
1PC	FRONT BUMPER FOG LAMP COVER O/S	17		\$145.00 X
1SET	FRONT BUMPER CLIPS	new		\$42.00
1PC	HEADLAMP O/S	one		\$1,675.00
1PC	FRONT FENDER O/S	Dis	419	\$684.00
1PC	FRONT FENDER INNER SHIELD O/S	Torn		\$162.00
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	new		\$40.00
1PC	FRONT FENDER INNER GARNISH O/S	17	68	\$88.00
1PC	FRONT KNUCKLE ARM O/S	Surf	393	\$605.00
1PC	FRONT KNUCKLE ARM BEARING O/S	new	150	\$292.00
1PC	FRONT SHOCK ABSORBER O/S	Surf	313	\$545.10
1PC	FRONT LOWER ARM O/S	Surf	380	\$550.00
1PC	FRONT TIE ROD O/S	Surf	95	\$105.00
1PC	FRONT DRIVE SHAFT O/S	17		\$1,885.00 X
1PC	FRONT STEERING RACK ASSY	Surf/TWI	1819	\$2,120.00
1PC	FRONT STEERING CROSS MEMBER	Dis/Surf	1600	\$1,950.00
1PC	FRONT DOOR O/S	Dis		\$1,281.00
1SET	FRONT DOOR FRAME BLACK STICKER O/S	new		\$60.00
1PC	FRONT DOOR MIRROR ASSY O/S	17		\$455.00 X
1PC	FRONT DOOR MIRROR COVER O/S	17		\$116.00 X
2PCS	FRONT DOOR HINGES O/S @\$ 90.00	Surf		\$180.00
1PC	FRONT DOOR CHECKER O/S	Surf		\$115.00
1PC	FRONT DOOR INNER SPEAKER O/S	17		\$250.00 X
1PC	FRONT DOOR INNER TRIM BOARD O/S	Re/Torn		\$650.00
1PC	FRONT DOOR GLASS REGULATOR O/S	Surf		\$390.00
1PC	FRONT DOOR INNER LOCK O/S	17/17		\$242.00
1PC	FRONT DOOR INNER RUBBER O/S	Torn		\$118.00
1PC	FRONT DOOR OUTER PILLAR O/S	Body		\$800.00
1PC	REAR DOOR O/S	Dis/Surf		\$939.00
1SET	REAR DOOR FRAME BLACK STICKER O/S	new		\$60.00
1PC	REAR DOOR INNER LOCK O/S	17		\$242.00 X
1PC	REAR DOOR INNER RUBBER O/S	17 NN		\$118.00 X
1PC	REAR DOOR HINGES O/S @\$90.00	17		\$180.00 X
1PC	REAR DOOR CHECKER O/S	17		\$115.00 X
1PC	REAR DOOR INNER TRIM O/S	17		\$650.00 X
1PC	REAR FENDER O/S	R		\$1,125.00 X
1SET	REAR FENDER OUTER STICKER O/S	new		\$30.00
1PC	REAR WHEEL HUB BEARING O/S	Page 320		\$450.00
1PC	REAR ABSORBER O/S	17		\$255.00 X

WZ

1PC	REAR AXLE BEAM	u7	\$1,150.00	X
1PC	REAR BUMPER	2	\$698.00	X
1SET	REAR BUMPER CLIPS	u7	\$50.00	X
1PC	REAR SPORT RIM O/S	cut/wrap	\$600.00	400 s/w
1PC	FRONT SPORT RIM O/S	wrap	\$600.00	400 s/w
1PC	Rocker panel o/s	Body	\$685.00	
			\$24,617.10	

(102)

TO CHECK WIRING	\$50.00	20
TO DIAGNOSTIC & REPROGRAMME SYSTEM	\$100.00	50
TO SPRAY RUST PROOFING	\$100.00	✓
TO TRANSFER BOTH O/S DOOR MECHANISM	\$120.00	✓
TO CONDUCT WHEEL ALIGNMENT	\$100.00	80
TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	\$450.00	350
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	\$250.00	120
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,800.00	1300
TO PUTTY & SPRAY PAINTING	\$1,800.00	1300
TOTAL	\$29,387.10	

P-13058
 102
 P-11752-20
 S.N-111650
 L- 3440
 16308.70
 202
 13046

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: