

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/SMR22010348/4943

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLW 1076L

at Workshop m/s

Rf.

of

Insured:

SMBS9575

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$60K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

9

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

061h

Vehicle: IN / OUT

Date:

Person Contacted:

L7A631154

Veh No:

SLW 1076L

Yr Regn:

30/01/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

K14 cerefs K3 c.c 1591

Colour

Brown

A/C: Insured / Std / NI / NA

Sp. Reading

270955

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNAFX411MJS761066

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

- off road

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

Farroad

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

LUMHO

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

12/10/22

D.O.I.

19/10/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/5 Frt, 10/5 Body &

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction Dep 11K.

headly 2210 Frt door 1542 Rear door 1361
have 6.4

8/11/22 1/5 @ 13,000 informed Alin. (head 16387.10, 56%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

9

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS. SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

7P

Lump Sum / I.B.I. (\$

13000

TOTAL

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 20006262D

Not Authorized
19/10/22
2/s \$13,000/
9 days.

VEHICLE No: SLW 1076L

NETT ITEM 316.50 s/N

1PC	FRONT BUMPER	Re/Torn	633.502 s/N	\$788.00	/502 s/N
1PC	FRONT BUMPER SIDE RETAINER O/S	one		\$32.00	
1PC	FRONT BUMPER FOG LAMP O/S	11		\$305.00	X
1PC	FRONT BUMPER FOG LAMP COVER O/S	11		\$145.00	X
1SET	FRONT BUMPER CLIPS	new		\$42.00	
1PC	HEADLAMP O/S	one		\$1,675.00	
1PC	FRONT FENDER O/S	Dis	419	\$684.00	
1PC	FRONT FENDER INNER SHIELD O/S	Torn		\$162.00	
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	new		\$40.00	
1PC	FRONT FENDER INNER GARNISH O/S	1m	68	\$88.00	
1PC	FRONT KNUCKLE ARM O/S	Surf	393	\$605.00	
1PC	FRONT KNUCKLE ARM BEARING O/S	new	150	\$292.00	
1PC	FRONT SHOCK ABSORBER O/S	Surf	313	\$545.10	
1PC	FRONT LOWER ARM O/S	Surf	380	\$550.00	
1PC	FRONT TIE ROD O/S	Surf	95	\$105.00	
1PC	FRONT DRIVE SHAFT O/S	11		\$1,885.00	X
1PC	FRONT STEERING RACK ASSY	Surf/TWI	1819	\$2,120.00	
1PC	FRONT STEERING CROSS MEMBER	Dis/Surf	1600	\$1,950.00	
1PC	FRONT DOOR O/S	Dis		\$1,281.00	
1SET	FRONT DOOR FRAME BLACK STICKER O/S	new		\$60.00	
1PC	FRONT DOOR MIRROR ASSY O/S	11		\$455.00	X
1PC	FRONT DOOR MIRROR COVER O/S	11		\$116.00	X
2PCS	FRONT DOOR HINGES O/S @\$ 90.00	Surf		\$180.00	
1PC	FRONT DOOR CHECKER O/S	Surf		\$115.00	
1PC	FRONT DOOR INNER SPEAKER O/S	11		\$250.00	X
1PC	FRONT DOOR INNER TRIM BOARD O/S	Re/Torn		\$650.00	
1PC	FRONT DOOR GLASS REGULATOR O/S	Surf		\$390.00	
1PC	FRONT DOOR INNER LOCK O/S	Tw/Tm		\$242.00	
1PC	FRONT DOOR INNER RUBBER O/S	Torn		\$118.00	
1PC	FRONT DOOR OUTER PILLAR O/S	Body		\$800.00	
1PC	REAR DOOR O/S	Dis/Surf		\$939.00	
1SET	REAR DOOR FRAME BLACK STICKER O/S	new		\$60.00	
1PC	REAR DOOR INNER LOCK O/S	11		\$242.00	X
1PC	REAR DOOR INNER RUBBER O/S	new		\$118.00	X
1PC	REAR DOOR HINGES O/S @\$90.00	11		\$180.00	X
1PC	REAR DOOR CHECKER O/S	11		\$115.00	X
1PC	REAR DOOR INNER TRIM O/S	11		\$650.00	X
1PC	REAR FENDER O/S	R		\$1,125.00	X
1SET	REAR FENDER OUTER STICKER O/S	new		\$30.00	
1PC	REAR WHEEL HUB BEARING O/S	Page	320	\$450.00	
1PC	REAR ABSORBER O/S	11		\$255.00	X

WZ

1PC	REAR AXLE BEAM	u7	\$1,150.00	X
1PC	REAR BUMPER	2	\$698.00	X
1SET	REAR BUMPER CLIPS	11	\$50.00	X
1PC	REAR SPORT RIM O/S	cut/wheel	\$600.00	400 s/w
1PC	FRONT SPORT RIM O/S	wheel	\$600.00	400 s/w
1PC	Rocker panel o/s	body	\$685.00	
			\$24,617.10	

(102)

TO CHECK WIRING	\$50.00	20
TO DIAGNOSTIC & REPROGRAMME SYSTEM	\$100.00	50
TO SPRAY RUST PROOFING	\$100.00	✓
TO TRANSFER BOTH O/S DOOR MECHANISM	\$120.00	✓
TO CONDUCT WHEEL ALIGNMENT	\$100.00	80
TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	\$450.00	350
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	\$250.00	120
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,800.00	1300
TO PUTTY & SPRAY PAINTING	\$1,800.00	1300
TOTAL	\$29,387.10	

P-13058
 102
 P-11752-20
 S.N-111650
 L-3440
 16308.70
 202
 13046

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: