



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2300873

INV Date 15/02/2023

Reference CC4/LPC22010355/Rpa3q2

Code LPC2

### PROFESSIONAL SERVICE FEE

Vehicle No. SMU 2618R  
Insured Veh. GV 1289D  
Claim No. 22/22/22/VC05/026435  
Policy No. Z22VC05011221  
Accident Date 17/10/2022  
Inspection Date 20/10/2022

| Description         | Total         |
|---------------------|---------------|
| Survey Inspection   | 250.00        |
| Digital Photographs |               |
| Transportation      |               |
| <b>Subtotal</b>     | <b>250.00</b> |
| <b>GST (8%)</b>     | <b>20.00</b>  |
| <b>Grand Total</b>  | <b>270.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                                                  |                 |                                                               |  |
|----------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------|--|
| LONPAC INSURANCE BHD<br>300 BEACH ROAD<br>#17-04/07 THE CONCOURSESINGAPORE 199555                                                      |                                                                                                                  |                 | Ref: CC4/LPC22010355/Rpa3q2<br>Date: 15/02/2023<br>Code: LPC2 |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                                                  |                 |                                                               |  |
| Insured Veh.                                                                                                                           | GV 1289D                                                                                                         | Veh. Inspected  | SMU 2618R                                                     |  |
| Policy No.                                                                                                                             | Z22VC05011221                                                                                                    | Coverage (\$)   | 0.00                                                          |  |
| Claim No.                                                                                                                              | 22/22/22/VC05/026435                                                                                             | Excess (\$)     | 0.00                                                          |  |
| Assign From                                                                                                                            |                                                                                                                  | Assign Date     | 18/10/2022                                                    |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                                                  |                 |                                                               |  |
| Make & Model                                                                                                                           | MAZDA 6 SEDAN 2.0L SP                                                                                            | c.c             | 1998                                                          |  |
| Engine No.                                                                                                                             | HIDDEN                                                                                                           | Year of Reg.    | 2017                                                          |  |
| Chassis No.                                                                                                                            | JM6GL1071H0118381                                                                                                | Colour          | WHITE                                                         |  |
| Odometer                                                                                                                               | 79477 KM                                                                                                         | Steering        | IN ORDER                                                      |  |
| Brakes                                                                                                                                 | IN ORDER                                                                                                         | Modification    | SPORTS RIM                                                    |  |
| General                                                                                                                                | FAIR                                                                                                             |                 |                                                               |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                                                  |                 |                                                               |  |
|                                                                                                                                        | Size                                                                                                             | Make            | Balance                                                       |  |
| R/H Front Tyre                                                                                                                         | 245/35Z R19                                                                                                      | FALKEN          | 6 mm                                                          |  |
| L/H Front Tyre                                                                                                                         | 245/35Z R19                                                                                                      | FALKEN          | 6 mm                                                          |  |
| R/H Rear Tyre                                                                                                                          | 245/35Z R19                                                                                                      | FALKEN          | 6 mm                                                          |  |
| L/H Rear Tyre                                                                                                                          | 245/35Z R19                                                                                                      | FALKEN          | 6 mm                                                          |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                                                  |                 |                                                               |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.<br>DAMAGES SEE DETAILS.                                                         |                                                                                                                  |                 |                                                               |  |
| <b>5. General Information</b>                                                                                                          |                                                                                                                  |                 |                                                               |  |
| Accident Date                                                                                                                          | 17/10/2022                                                                                                       | Inspection Date | 20/10/2022                                                    |  |
| Survey held at                                                                                                                         | KAN FOOK SING MOTOR WORKSHOP<br>BLK.8 JTC DEFU INDUSTRIAL CITY<br>#04-29 DEFU SOUTH STREET 1<br>SINGAPORE 533758 |                 |                                                               |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                                                  |                 |                                                               |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                                  |                 |                                                               |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                                                  |                 |                                                               |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                                                  |                 | 3 Working Days                                                |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMU 2618R

| Qty | Description of Parts                                                                                                                                   | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>                                                                                                                     |           |                           |                   |
| 1   | REAR LAMP RH                                                                                                                                           | CRACKED   | 1,593.00                  | 1,593.00          |
| 1   | REAR BUMPER                                                                                                                                            | CUT       | 1,266.00                  | 1,266.00          |
| 1   | REAR BUMPER SIDE RETAINER RH                                                                                                                           | * CHECK   | 59.00                     | -                 |
| 10  | REAR BUMPER CLIP @\$5.00                                                                                                                               | NECESSARY | 50.00                     | 50.00             |
|     | LESS 20% DISCOUNT                                                                                                                                      |           | -593.60                   | -581.80           |
|     |                                                                                                                                                        |           | 2,374.40                  | 2,327.20          |
|     | <b><u>LABOUR</u></b>                                                                                                                                   |           |                           |                   |
|     | TO CHECK WIRING SYSTEM.                                                                                                                                |           | 50.00                     | 30.00             |
|     | TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS.                                                                      |           | 420.00                    | 300.00            |
|     | SPRAYPAINTING CHARGE.                                                                                                                                  |           | 420.00                    | 400.00            |
|     |                                                                                                                                                        |           | 890.00                    | 730.00            |
|     | <b>GRAND TOTAL</b>                                                                                                                                     |           | <b>3,264.40</b>           | <b>3,057.20</b>   |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS<br/>(TO ITS PRE-ACCIDENT CONDITION)<br/>(REPAIR COST NOT CONCLUDE)<br/>(EXCLUDE CHECK ITEMS S\$47.20 NETT)</b> |           |                           | <b>2,450.00</b>   |

Report Ref No. CC4/LPC22010355/Rpa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SMU 2618R

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

